

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

Co. Reg No. 201202259N

LKK
Not Authorized
15/11/24
1/5 @ 1800

Name : Lee Chin Leong (91026757)

Accident Date : 19-Oct-24

Vehicle No : FBD4559J (COE: 110309-280229)

Vehicle Model : Yamaha FZ150I

Estimated Repair Costs

4 hrs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Fork inner tubes	\$ Sur 640.00 X
2	Fork outer tubes	\$ Sur 660.00 X
1	Fork under bracket	\$ 11 285.00 X
1	Front rim	\$ 11 580.00 X
1	Front fender	\$ 11 220.00 X
2	Front signal	\$ 60 120 200.00 1pc
1	Meter assy	\$ 11 620.00 X
2	Side mirror - R/L	\$ 70 140.00 1pc
1	Head lamp	\$ 11 480.00 X
1	Lampstay	\$ 11 320.00 X
1	Handle bar	\$ 320 280.00 X
1	Handle bar balancer	\$ 50 90.00 X
1	Hand grip (1 set)	\$ 11 80.00 X
1	Clutch lever	\$ 11 115.00 X
1	Fuel tank	\$ 11 620.00 X
2	Front footrest	\$ 11 145.00 X
2	Front footrest brackets	\$ 11 380.00 X
1	Gear pedal	\$ 110 135.00 X
2	Rear footrest	\$ 11 155.00 X
2	Rear signals	\$ 11 200.00 X
1	Rear fender	\$ 105 280.00 X
1	Rear lamp	\$ 11 420.00 X
1	Swing arm	\$ 11 650.00 X
1	Swing arm shaft	\$ 11 145.00 X
1	Rear rim	\$ 11 680.00 X
1	Rear rim shaft	\$ 11 125.00 X
1	Fairing assy front Cowley	\$ 250 880.00 X
1	Exhaust assy	\$ 11 750.00 X
1	Exhaust protector	\$ 11 125.00 X
		\$ 10,400.00
	Less 10%	\$ 1,040.00
		\$ 9,360.00

EROFIA MOTOR TRADING PTE LTD

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883
Tel : 67527740 Fax : 67528669
Co. Reg No. 201202259N

Name : Lee Chin Leong (91026757)

Accident Date : 19-Oct-24

Vehicle No : FBD4559J (COE: 110309-280229)

Vehicle Model : Yamaha FZ150I

Estimated Repair Costs

Special Nett Items

- | | |
|---|-----------------------|
| 1 | Number plate (1 set) |
| 2 | Fork oils |
| 2 | Fork oil seals |
| 1 | Steering cone (1 set) |
| 1 | Rear box |
| 1 | Rear box bracket |

\$ 11	28.00	X
\$ 11	30.00	✓
\$ 11	56.00	40
\$ 11	95.00	X
\$ 117	480.00	20
\$ 11	180.00	X
\$	869.00	

S/No.

Labour


- | | |
|---|---|
| 1 | To provide towing service (LOD) S\$70.00 |
| 2 | To check wiring and reset headlamp focusing |
| 3 | To repair body frame |
| 4 | To provide labour |

refer to \$ 200	-	X
\$ 11	80.00	X
\$ 11	420.00	X
\$	480.00	300
\$	980.00	

Grand Total

\$	11,209.00
----	-----------

Singapore Dollars: Eleven Thousand Two Hundred and Nine only


EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-1860
102
1674
350
300