

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 18 Nov 2024

**Preliminary Advice**

Vehicle No	: SNG3785X	Accident Date	: 07/11/2024
Make	: MERCEDES-BENZ E200	Policy No.	: MCF24B00000800
Assignment Date	: 14/11/2024	Excess	: S\$1,000.00
Date of Inspection	: 15/11/2024	Est. Duration of Repair	: 6
Inspection At	: DIPLOMAT PARTS PTE LTD (HQ) 209 PANDAN GARDENS SINGAPORE 609339		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,603.15
Revised Amount	:S\$	9,877.15
Check Items (Estimated)	:S\$	337.70
Total	:S\$	10,214.85
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	225,000.00
COE / PARF Rebate	:S\$	121,035.00
Salvage Value	:S\$	
Margin for Repair	:S\$	103,965.00

**Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : THE VEHICLE REPAIR ON PART BY PART BASIS.  
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.