



簡福星摩嘜王廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: Blk 8 JTC Defu Industrial City #04-29 Defu South Street 1, S533758

Tel: (65) 6747 9560, 6743 5344 • Fax: (65) 6748 1006

E-mail: ryan@kanfs.net / patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-13, Singapore 417883

Tel: (65) 6481 5150 • Fax: (65) 6481 8683

ATTORNEY GENERAL CHAMBERS
1 COLEMAN STREET #10-00 S(0617)

DATE : 27-11-2024

VEHICLE NO. : SKC2018R
ACCIDENT DATE : 10-11-2024 13:00
THIRD PARTY REF. : QX2198Y

ATTN: ATTORNEY GENERAL CHAMBERS

SUPPLEMENTARY COST OF REPAIR TO VEHICLE SKC2018R TOYOTA C-HR

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
LABOUR CHARGES		
1	REMOVE & REFIX REAR WINDSCREEN	150.00
TOTAL (D)		150.00
SUPPLEMENTARY TOTAL		150.00

ATTORNEY GENERAL CHAMBERS
1 COLEMAN STREET #10-00 S(0617)

INVOICE NO : TEST
DATE : 27-11-2024

VEHICLE NO. : SKC2018R
ACCIDENT DATE : 10-11-2024 13:00
THIRD PARTY REF. : QX2198Y

ATTN: ATTORNEY GENERAL CHAMBERS
INVOICE COST OF REPAIRS TO VEICLE SKC2018R TOYOTA C-HR

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	TAIL-GATE	1450.30
1	TAIL-GATE GARNISH	1225.60
1	REAR BUMPER TOP	703.60
1	REAR BUMPER LOWER	687.45
1	REAR BUMPER REINFORCEMENT	422.30
2	REAR BUMPER SIDE RETAINER @\$152.20	152.20
10	REAR BUMPER CLIP @\$5.50	55.00
1	REAR WINDSCREEN MOULDING	256.50
1	TAIL-GATE EMBLEM	127.50
1	TAIL-GATE CHR EMBLEM	98.50
		5,178.95
LESS 25 %		
TOTAL (A)		1,294.74
		3,884.21

SPECIAL NETT ITEMS

1	REAR BUMPER REVERSE SENSOR	200.00
1	REAR WINDSCREEN GUM	60.00
TOTAL (C)		260.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM	30.00
1	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS,WELD/CUT,PANEL BE- ATING	400.00

VEHICLE NO. : SKC2018R
ACCIDENT DATE : 10-11-2024 13:00
THIRD PARTY REF. : QX2198Y

<u>QTY</u>	<u>PARTS DESCRIPTION</u>	<u>AMOUNT (SG\$)</u>
1	SPRAY PAINTING	450.00
1	REMOVE & REFIX REAR WINDSCREEN	150.00 120
TOTAL (D)		1,030.00 1000
TOTAL REPAIR COST :		5,174.21
G S T % :		465.67
INVOICE AMOUNT :		5,639.88