



DICKSON GROUP

Your Trusted Automotive Solutionist

DICKSON AUTO CARE CENTRE PTE LTD
29 UBI ROAD 4, DICKSON AUTO CENTRE
SINGAPORE 408619
TEL: 6668 1122 | FAX: 6668 1123

Steve CLKK)
14/11/24, 4.17pL
m n
L/S

QUOTATION

QUOTATION FOR

NAME: Auto & General Insurance (Singapore)
Pte. Ltd
COMPANY NAME: Auto & General Insurance (Singapore)
Pte. Ltd
STREET ADDRESS: 190 Clemenceau Avenue, #03-01
Singapore Shopping Centre
POSTAL CODE: Singapore 239924
PHONE: 6221 2111

DATE: 13/11/2024

REF: SD0824BC0003

VEHICLE NO: SMU1580X

MAKE: HONDA

MODEL: VEZEL

PREPARED BY: XIANG

8-6 days (not include end pay)

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
LABOUR							
1	TO REMOVE & REPLACE BUMPER FRONT, HEADLAMPS, BONNET, BUMPER REINFORCEMENT, TAILGATE, TAILAMPS, BUMPER REAR, REAR PANEL, BOOT FLOOR & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$1,800.00	\$ 1,800.00		\$ 1,800.00
2	TO SPRAY BUMPER FRONT, BONNET, BUMPER REINFORCEMENT, TAILGATE, BUMPER REAR, REAR PANEL & BOOT FLOOR	1		\$1,700.00	\$ 1,700.00		\$ 1,700.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$200.00	\$ 200.00		\$ 200.00
4	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$200.00	\$ 200.00		\$ 200.00
5	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$150.00	\$ 150.00		\$ 150.00
6	TO REMOVE & REFIT WINDSCREEN REAR	1		\$150.00	\$ 150.00		\$ 150.00
7	TO TRANSFER SENSORS REAR	1		\$100.00	\$ 100.00		\$ 100.00
PARTS							
1	BUMPER FRONT COVER / DEF	1		\$801.70	\$ 801.70		\$ 801.70
2	BUMPER CLIPS - MC	10		\$4.20	\$ 42.00		\$ 42.00
3	BUMPER SIDE RETAINER LH - BR	1		\$20.60	\$ 20.60		\$ 20.60
4	BUMPER SIDE RETAINER RH X nn	1		\$20.60	\$ 20.60		\$ 20.60
5	HEADLAMP ASSY LH - BR	1		\$2,108.50	\$ 2,108.50		\$ 2,108.50
6	HEADLAMP ASSY RH X nn	1		\$2,108.50	\$ 2,108.50		\$ 2,108.50

-890- 1200

-1000- 1400

30

X

30

120

30

= 2810

/

30 /

/

1784.00 /

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
7	GRILLE FRONT 10442228A 1 ? / BR	1		\$351.80	\$ 351.80		\$ 351.80 /
8	GRILLE FRONT MOULDING (CHROME) (12mm) - BR	1		\$385.10	\$ 385.10		\$ 385.10 284 /
9	GRILLE BADGE (LOGO) / n/c	1		\$27.80	\$ 27.80		\$ 27.80 /
10	BONNET / ON	1		\$892.30	\$ 892.30		\$ 892.30 /
11	BONNET HINGE LH X nn	1		\$65.80	\$ 65.80		\$ 65.80
12	BONNET HINGE RH X nn	1		\$65.80	\$ 65.80		\$ 65.80
13	GRILLE FRONT CENTRE MOULDING (CHROME) - BR	1		\$95.20	\$ 95.20		\$ 95.20 /
14	BUMPER REINFORCEMENT FRONT 1 ? / DD	1		\$321.80	\$ 321.80		\$ 321.80 /
15	BUMPER SHOCK ABSORBER FRONT ? 1 x nn	1		\$150.00	\$ 150.00		\$ 150.00
16	AIRCOND CONDENSER X nn	1		\$568.20	\$ 568.20		\$ 568.20
17	NUMBER PLATE FRONT / BR	1		\$25.00	\$ 25.00		\$ 25.00 /
18	NUMBER PLATE FRONT HOLDER - BR	1		\$30.00	\$ 30.00		\$ 30.00 /
19	TAILGATE / ON	1		\$1,100.90	\$ 1,100.90		\$ 1,100.90 /
20	TAILGATE LOCK ? / Jammed	1		\$178.20	\$ 178.20		\$ 178.20 /
21	TAILGATE STRIKER X nn	1		\$38.30	\$ 38.30		\$ 38.30
22	TAILGATE BADGE (LOGO) 222222 1 ? x nn	1		\$22.50	\$ 22.50		\$ 22.50
23	TAILGATE BADGE (VEZEL) / n/c	1		\$68.20	\$ 68.20		\$ 68.20 /
24	TAILGATE BADGE (HYBRID) / n/c	1		\$70.50	\$ 70.50		\$ 70.50 /
25	TAILAMP OUTER LH ? x nn	1		\$513.20	\$ 513.20		\$ 513.20
26	TAILAMP OUTER RH ? x nn	1		\$513.20	\$ 513.20		\$ 513.20
27	TAILAMP INNER LH ? x nn	1		\$449.50	\$ 449.50		\$ 449.50
28	TAILAMP INNER RH ? x nn	1		\$449.50	\$ 449.50		\$ 449.50
29	TAILGATE APERTURE WEATHERSTRIP ? x nn	1		\$107.80	\$ 107.80		\$ 107.80
30	TAILGATE COVERBOARD ? / CRU	1		\$215.30	\$ 215.30		\$ 215.30 /
31	COVERBOARD CLIPS ? / Nec	10		\$4.20	\$ 42.00		\$ 42.00 20 /
32	BUMPER REAR COVER LH / CR4	1		\$195.00	\$ 195.00		\$ 195.00 /

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT
33	BUMPER REAR COVER RH <i>X nn</i>	1		\$195.00	\$ 195.00		\$ 195.00
34	BUMPER REAR LOWER COVER <i>/ nn</i>	1		\$532.10	\$ 532.10		\$ 532.10
35	REFLECTOR REAR LH <i>? x nn</i>	1		\$182.50	\$ 182.50		\$ 182.50
36	REFLECTOR REAR RH <i>X nn</i>	1		\$182.50	\$ 182.50		\$ 182.50
37	REAR PANEL <i>? / DD</i>	1		\$411.90	\$ 411.90		\$ 411.90
38	REAR PANEL INNER TRIM <i>? / DEF</i>	1		\$92.30	\$ 92.30		\$ 92.30
39	BOOT FLOOR CARPET <i>? x nn</i>	1		\$325.60	\$ 325.60		\$ 325.60
40	BOOT FLOOR TRAY <i>? x nn</i>	1		\$226.90	\$ 226.90		\$ 226.90
41	WINDSCREEN MOULDING REAR <i>/ nk</i>	1		\$120.70	\$ 120.70		\$ 120.70
42	EXHAUST SILENCER REAR <i>X nn</i>	1		\$726.30	\$ 726.30		\$ 726.30
43	BOOT FLOOR <i>? x Repair</i>	1		\$1,135.70	\$ 1,135.70		\$ 1,135.70
44	MOULDING WHEEL ARCH REAR LH <i>/ 1 (RM)</i>	1		\$292.10	\$ 292.10		\$ 292.10
45	MOULDING WHEEL ARCH REAR RH <i>X nn</i>	1		\$292.10	\$ 292.10		\$ 292.10
46	SENSOR BUMPER REAR (SET) <i>/ BR</i>	1		\$135.00	\$ 135.00		\$ 135.00
47	AIRCOND GAS <i>X nn</i>	1		\$80.00	\$ 80.00		\$ 80.00
48	FLOOR BOARD SEALANT <i>? (end panel sealant)</i>	1 / Nec		\$100.00	\$ 100.00		\$ 100.00
49	WINDSCREEN SEALANT <i>(Pw) - nk</i>	1		\$80.00	\$ 80.00		\$ 80.00
SUBTOTAL					\$ 21,455.50	SUBTOTAL	\$ 21,455.50
GST 9%					\$ 1,931.00	GST 9%	\$ 1,931.00
TOTAL					\$ 23,386.50	TOTAL	\$ 23,386.50

REMARKS:

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD



(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

(AUTHORISED SIGNATURE)

= 9461.44 + 346.80 (Supp)
= 9808.24

L/S - 7846.95
= 7850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____