

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	UNITED OVERSEAS INSURANCE LTD		Ref:	CS3/UOI24110294/Rqp3m4	
	146 ROBINSON ROAD #02-01 UOI BUILDING SINGAPORE 068909		Date:	21/11/2024	
	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Code:	UOI2	
1.	1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	YN 6700D	Veh. Inspected	SLN 2005H	
	Policy No.	-	Coverage	0	
	Claim No.	M11D00232411	Excess	\$0.00	
	Assign From	JOEY TAY	Assign Date	14/11/2024	
2. Vehicle Details					
	Make & Model	MERCEDES BENZ S300L	C.C	2997	
	Engine No.	27294631115203	Year of Reg.	15/05/2009	
	Chassis No.	WDD2211542A265967	Colour	GREY	
	Odometer	221026 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	FAIR	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	255/45 R18	MICHELIN	6	
	L/H Front Tyre	255/45 R18	MICHELIN	6	
	R/H Rear Tyre	255/45 R18	MICHELIN	6	
	L/H Rear Tyre	255/45 R18	MICHELIN	6	
4. Description of Damages					
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
5.	General Information				
	Accident Date	10/11/2024	•	14/11/2024 (17:07)	
	Survey held at TT MOTORSPORT PTE LTD - 48 TOH GUAN ROAD EAST #01-103 ENTERF SINGAPORE 608586				
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$7,000-\$8,000					
D) 1					

MRB

MOHAMMED RASUL BIN MOHD YUNUS

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.