

SERVE YOU MOTOR PTE LTD
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265, SINGAPORE 569536
 TEL. NO: 64810555 / FAX NO. 64831654
 E-MAIL: elainesyms@gmail.com

Ins: Income Insurance Limited
 Owner: Golden Top Travel
 Registration no. : PZ 3888 J / ISUZU LT434P
 Accident Date: 8/11/2024
 Date : 14-Nov-24

Quotation no: 38881106

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

- | | | |
|---|---|---|
| 1 | 1 | Rear corner panel |
| 2 | 1 | Rear RH side Compartment door with Grille cover |
| 3 | 1 | Rear (RH) Tail Lamp Assy |

n \$987.00 *x*
warp \$1,388.00 *✓*
Bu \$1,663.80 *✓*
 \$4,038.80
 Less 10 % \$403.88
\$3,634.92

LABOUR & MISC CHARGES

- | | |
|---|---|
| 1 | To knock out the accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts. |
| 2 | To remove and replace rear tail lamp and check for the wiring |
| 3 | Supply spray paint material (multi-color) and necessary items to respray on the accident damage area and other affected area / panel. |

6001
 \$1,800.00
201
 \$120.00
8001
 \$2,300.00

TOTAL

\$4,220.00
\$7,854.92

Total Parts and Labour Cost of Repair

Not Withheld
L1 Rep \$3300/h
Penalty After Repair
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: