

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/AIG24110298/EMA3Q2**Date:** 12/03/2025**REFERENCE**

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : SMH7909L**Insured Vehicle No :** SLD4511C

Date of Loss: 30/10/2024

Nature of Claim: TP

Claim No: 0850521365SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMH7909L**

Make & Model: AUDI A4, 2.0 SEDAN TFSI S-TRONIC (NAV) (A) Engine No: CVK075526

Reg. Date: 01/02/2019 (Man. Year: 2018)

Chassis No: WAUZZZF41KN006291

Colour: Blue

Odometer: 116435 km

Engine Capacity: 1984 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40Z R18

Rear Tyre Size: 245/40Z R18

Front Left Side: Michelin 5 mm

Rear Left Side: Michelin 5 mm

Front Right Side: Michelin 5 mm

Rear Right Side: Michelin 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,081.00	3,379.28	6,701.72	66.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,052.00	3,852.00	2,200.00	36.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,133.00	7,231.28	8,901.72	55.18
+ GST 9.00/9.00% (S\$)	1,451.97	650.82	801.15	55.18
Nett Amount (S\$)	17,584.97	7,882.10	9,702.87	55.18
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		8,284.28		

INSPECTION

Date of Assignment: 18/11/2024

Date Inspected: 18/11/2024

Inspected At:

Premium Automobiles Pte Ltd (HQ)

55 UBI ROAD 1

Singapore 408699

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** Daphne Lee Mooi Ngiuk*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Dented	3,647.00 FS	*2,917.60 FS
2	1		*REAR DOOR OUTER SEAL RH	Necessary	255.00 FS	*204.00 FS
3	1		*REAR DOOR SEALING STRIP RH	Not Necessary	24.00 FS	*- FS
4	1		*REAR DOOR CATCH RH	Loose	150.00 FS	*120.00 FS
5	1		*REAR DOOR ATTACHMENT PARTS RH	Not Necessary	1,010.00 FS	*- FS
6	1		*REAR DOOR HANDLE TRIM RH	Repair	193.00 FS	*- FS
7	1		*REAR BUMPER	Repair	3,595.00 FS	*- FS
8	1		*REAR BUMPER FIXING PARTS RH	Not Necessary	502.00 FS	*- FS
9	1		*REAR LIGHT REFLECTOR RH REAR	Not Necessary	49.00 FS	*- FS
10	1		*BONDING AGENT	Necessary	54.00 FS	*43.04 FS
11	1		*CLEANING SOLUTION	Necessary	92.00 FS	*72.88 FS
12	1		*APPLICATOR	Necessary	10.00 FS	*8.00 FS
13	1		*SUNDRIES	Necessary	500.00 FS	*13.76 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	10,081.00	3,379.28
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR	New	360.00	360.00
2	TO REMOVE AND TRANSFER RHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES INSPECT FOR DAMAGES	New	350.00	350.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR TO REPAIR RHS REAR FENDER REOGNIZE CRASH MANAGEMENT COMPONENTS REINSTALL ALL PARTS REMOVED	New	2,450.00	1,000.00
4	TO RESPRAY REAR BUMPER ,RHS REAR FENDER ,RHS REAR DOOR AND RHS REAR DOOR HANDLE	New	2,600.00	1,850.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	292.00	292.00
Gross Labour Cost (\$\$)			6,052.00	3,852.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >