

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0860/2024/KS
DATE : 14-Nov-24
WIP : 38492

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 14/11/2024

YOUR INSURED VEH NO : SLD 4511 C

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR JOSEPH TITUS
ADDRESS : 10F BRADDELL VIEW
#06-21
SINGAPORE 579725
TELEPHONE : HP +65 96700626
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : D 300156772 QMY
VEHICLE NO : **SMH 7909 L**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI
MODEL YEAR : 1/2/2019
ENGINE NO : CVK 075526
CHASSIS NO : WAUZZZF41KN006291
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Oct-24
PLACE OF ACCIDENT : 5 LOWER KENT RIDGE ROAD, SINGAPORE 119074
NUS HOSPITAL CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMH 7909 L**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO REMOVE AND TRANSFER RHS REAR DOOR MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	350.00	
3	TO DISMANTLE AND RENEW REAR BUMPER AND RHS REAR DOOR. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,450.00	
4	TO RESPRAY REAR BUMPER, RHS REAR FENDER, RHS REAR DOOR AND RHS REAR DOOR HANDLE.	\$	2,600.00	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	
TOTAL LABOUR CHARGES		:	\$ 6,052.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMH 7909 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR DOOR - RH	1	\$ 3,647.00	
2	REAR DOOR OUTER SEAL - RH	1	\$ 255.00	
3	REAR DOOR SEALING STRIP - RH	1	\$ 24.00	
4	REAR DOOR CATCH - RH	1	\$ 150.00	
5	REAR DOOR ATTACHMENT PARTS - RH	1	\$ 1,010.00	
6	REAR DOOR HANDLE TRIM - RH	1	\$ 193.00	
7	REAR BUMPER	1	\$ 3,595.00	
8	REAR BUMPER FIXING PARTS - RH	1	\$ 502.00	
9	REAR LIGHT REFLECTOR - RH REAR	1	\$ 49.00	
10	BONDING AGENT	1	\$ 54.00	
11	CLEANING SOLUTION	1	\$ 92.00	
12	APPLICATOR	1	\$ 10.00	
13	SUNDRIES		\$ 500.00	
TOTAL SPARE PARTS		:	\$ 10,081.00	
TOTAL LABOUR CHARGES		:	\$ 6,052.00	
GRAND TOTAL		:	\$ 16,133.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT