



Kenrick
96910663

Not authorized
Refuse B4 painting
4 days
11 Sep @ 5800h

6453 4730
6457 1931
enquiry@sh-motor.com

WORKSHOP

160 Sin Ming Drive
#07-02 Sin Ming AutoCity
Singapore 575722

S&H Motor Pte Ltd

Co. Reg. No.: 198701322K
GST Reg. No.: M2-0076269-0

M/s First Capital Insurance Ltd
36 Robinson Road #16-01
City House
Singapore 068877

File No: SH/2024/0178/TP
Date: 5/11/2024

Estimated cost of repair for vehicle no: SND4845R Mazda 6
Accident involving vehicle no: SND4845R & SH7941X On 2/11/2024

Description	Quantity	List Price
Front bumper	1	\$ Bu 350.00 ✓
Front bumper side retainer lh	1	\$ Div 22.00 ✓
Front bumper side grille lh	1	\$ Su 32.00 X
Front bumper sponge	1	\$ Su 75.00 X
Head lamp lh 4759.20	1	\$ mfg cost 5,140.00 ✓
Front fender lh	1	\$ Bu 373.00 ✓
Front fender inner shield lh	1	\$ Div 125.00 ✓
Center grille	1	\$ MLC (CM) 673.00 X
Center grille base	1	\$ Su 165.00 X
Center grille chrome trimming lh	1	\$ Su 300.00 X
Center grille "Mazda Logo" emblem	1	\$ nu 68.00 X
Center grille top garnish	1	\$ Su 520.00 X
Front rim lh 1144.88	1	\$ Div 1,225.00 ✓
Front knuckle lh	1	\$ Bu 468.17 ✓
Front knuckle bearing lh	1	\$ nu 166.50 ✓
Front knuckle bearing hub lh } 566.70	1	\$ Bu 769.93 ✓
		\$ 10,472.60
	LESS 10% 20%	\$ 1,047.26
		\$ 9,425.34

Special Nett

Front bumper clip	set	\$ nu 40.00 ✓
Front fender inner shield clip lh	set	\$ nu 30.00 ✓

Labour

To dismantle, replace, cut, weld, knock out dents to straighten accident damaged parts.	\$	500.00 400l
To conduct wheel alignment	\$	60.00 ✓
Remove & refix/replace front undercarriage work lh	\$	200.00 90l
Wiring /bulb checking/focusing	\$	40.00 20l
To putty & spray paint accident damaged parts and adjacent panels	\$	600.00 400l
	\$	10,895.34

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: