

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: 23/23/24/VP02/418286 Date: 20th Nov 2024

Our Ref: CS1/LPM24110300/Enh3e2

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank No. 6 Jalan Sultan Sulaiman 50000 Kuala Lumpur, Malaysia (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMQ 4563Y INSURED VEHICLE: JQR 9755

ACCIDENT DATE: 15/10/2023

We thank you for your instruction on 14/11/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMQ 4563Y from M/s T C Automobile Assessors.
- b) Polis Diraja Malaysia of Vehicles SMQ 4563Y and JQR 9755.
- c) Colour damaged vehicle photographs of SMQ 4563Y.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SMO 4563Y

Make & Model : Mercedes Benz GLC200 (R18 LED)

Year of Registration : 2017

Chassis Number : WDC2539422F344486

Engine Capacity : 1991 cc

- 2. We recommend that the repairs of the entire damage require about <u>4 (Four)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.