

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. : SAC2400984

INV Date : 14-10-2024

Reference CD/LPC24060274/Apa3

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMA 880S
Insured Veh. GBL 9614H
Claim No. 23/24/24/VC05/029443
Policy No. Z23VC05019740
Accident Date 24/06/2024
Inspection Date 27/06/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24060274/Apa3
300 BEACH ROAD	Date:	14/10/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	GBL 9614H	Veh. Inspected	SMA 880S
Policy No.	Z23VC05019740	Coverage	0
Claim No.	23/24/24/VC05/029443	Excess	\$0.00
Assign From	ENG HUEY NI	Assign Date	27/06/2024

2. Vehicle Details

Make & Model	BMW 520I	C.C	1997
Engine No.	A1021273N20B20B	Year of Reg.	27/02/2016
Chassis No.	WBA5A32080D792339	Colour	BEIGE
Odometer	143349 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45R18	PIRELLI	6
L/H Front Tyre	245/45R18	PIRELLI	6
R/H Rear Tyre	245/45R18	PIRELLI	6
L/H Rear Tyre	245/45R18	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	24/06/2024	Inspection Date	27/06/2024
Survey held at	SUCCESS UNITED PTE LTD 2 KAKI BUKIT AVE 2 #01-33 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMA 880S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DEFORMED	\$2,195.40	\$1,685.00
1	FRONT BUMPER SIDE HOLDER RH	NOT NECESSARY	\$49.57	\$0.00
1	FRONT HEADLAMP ASSY RH	NOT NECESSARY	\$5,064.68	\$0.00
	LESS 5.00% DISCOUNT		(\$365.48)	(\$84.25)
			\$6,944.17	\$1,600.75
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
8	FRONT BUMPER CLIPS	NECESSARY	\$96.00	\$30.00
			\$96.00	\$30.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REPAIR AND REPLACE DAMAGED BODYPARTS, REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT.		\$400.00	\$200.00
	TO PUTTY AND RESPRAY PAINTING OF FRONT BUMPER		\$500.00	\$200.00
			\$900.00	\$400.00
GRAND TOTAL			\$7,940.17	\$2,030.75
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$1,600.00
Report Ref No: CD/LPC24060274/Apa3				

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 1 of 3)

PHOTOGRAPHS FOR VEHICLE NO. : SMA 880S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 2 of 3)

PHOTOGRAPHS FOR VEHICLE NO. : SMA 880S



PHOTOGRAPHS FOR VEHICLE NO. : SMA 880S



PHOTOGRAPHS FOR VEHICLE NO. : SMA 880S

