



Auto Consultants

Co.Reg no: 53439395X

TAX INVOICE

Our Ref: INV/22/07/002(M)

Date: 16/08/2022

To: MR LEE KAR WEI
Repairer Company: 168 Auto Services Pte Ltd
Address: 176 Sin Ming Drive #05-14 Sin Ming Auto Care
Postal Code: 575721

Assignment Date: 18/07/2022
Inspected Vehicle No.: SJC2052C
Date of accident: 17/07/2022

DESCRIPTION	AMOUNT (\$)
SURVEY	
PHOTOS - 68 PICTURES	\$ 1,500.00
TRANSPORTATION	
TOTAL	\$ 1,500.00

(DOLLARS: ONE THOUSAND AND FIVE HUNDRED ONLY)

Notes:

- 1) Payment to be made via Cash Cheque or Cash
- 2) For enquiries on this invoice. Please feel free to contact us.



Official Stamp

Computer generated, Signature not required

SL Auto Consultants
Accident Claims . Survey Services . Professional Advice
Add: 129 Lorong Ah Soo #05-352 Singapore 530129
Email: slautoconsultants@gmail.com / Mobile No: 90067276



Auto Consultants

Co.Reg no: 53439395X

VEHICLE INSPECTION REPORT

Our Ref: SLVDIR/22/07/002

Date: 18/07/2022

To: MR LEE KAR WEI
Repairer Company: 168 Auto Services Pte Ltd
Address: 176 Sin Ming Drive #05-14 Sin Ming Auto Care
Postal Code: 575721

REFERENCES

Claim Type:	THIRD PARTY	Date of Accident:	17/07/2022
Third party vehicle:	SJC2052C	Date of Inspection:	18/07/2022
Insured Vehicle:	NIL		

DAMAGED VEHICLE PARTICULARS

Registration Plate No:	SJC2052C	Engine Modification:	NIL
Model/ Make:	Toyota Corolla Axio	Pre-accident damage:	NIL
Date of Registration:	1/2/2008	General Condition:	Fair
Chassis No:	NZE1416065565	General Paint Colour:	Grey
Engine No:	1NZC883125	Steering:	Good
Engine Capacity:	1496cc	Handbrake:	Good
Odometer No:	305782	Footbrake:	Good

TYRES CONDITION

<u>Front Right</u>		<u>Rear Right</u>	
Make:	Westlake	Make:	Continental
Size:	205 55 R16	Size:	205 55 R16
	60%		50%
<u>Front Left</u>		<u>Rear Left</u>	
Make:	Westlake	Make:	Yokohama
Size:	205 55 R16	Size:	205 55 R16
	60%		50%

The above percentages represent the remaining life of tyre treads

SL Auto Consultants
Accident Claims . Survey Services . Professional Advice
Add: 129 Lorong Ah Soo #05-352 Singapore 530129
Email: slautoconsultants@gmail.com / Mobile No: 90067276

VEHICLE REPAIR COST

Descriptions	Repairer SGD	Adjuster SGD
Parts	\$ 11,504.85	\$ 9,460.43
Special Nett	\$ 1,600.00	\$ 670.00
Labour	\$ 6,980.00	\$ 4,060.00
Calculated Cost SGD	<u>\$ 20,084.85</u>	<u>\$ 14,190.43</u>

Recommended Lump Sum Repair Cost SGD **\$ 11,352.34**
Estimate Repair Duration **10 Working Days**
Survey Inspection Location 168 Auto Services Pte Ltd
Survey Inspection Address 176 Sin Ming Drive #05-14 Sin Ming Auto Care
Singapore 575721

DESCRIPTION OF DAMAGE

Rear RHS Portion

REMARKS

We have inspected the actual damages found on the vehicle and recommended the replacement of parts and repairs accordingly. The estimated repair cost is \$11,352.34. The repairer has to agree to undertake the repairs at our adjusted lump sum amount of \$11,350.00.

We have not authorized the repair. Under normal circumstances, estimated 10 working days are required.

We are pleased to advise that the inspection work was carried out accordingly and hereby submit our Inspection Report.

The inspection was conducted on a "WITHOUT PREJUDICE" basis.



Automotive Appraiser: Samuel Phun

SL Auto Consultants
Accident Claims . Survey Services . Professional Advice
Add: 129 Lorong Ah Soo #05-352 Singapore 530129
Email: slautoconsultants@gmail.com / Mobile No: 90067276

ASSESSMENT REPORT FOR VEHICLE NO: SJC2052C

LIST ITEMS

No	Qty	Description	CONDITION	REPAIRER Amount SGD	ADJUSTER Amount SGD
1	1	Rear Bootlid	Dented	\$ 1,296.90	\$ 1,296.90 /
2	1	Rear Bootlid Outer Garnish	Serviceable	\$ 399.90	\$ -
3	2	Rear Bootlid Number Plate Lamp	Serviceable	\$ 220.00	\$ -
4	1	Rear Bootlid Logo	Necessary	\$ 95.00	\$ 95.00 /
5	1	Rear Bootlid 'AXIO' Emblem	Necessary	\$ 98.00	\$ 98.00 /
6	1	Rear Bootlid 'X' Emblem	Necessary	\$ 88.00	\$ 88.00 /
7	1	Rear Bootlid Lock	Distorted	\$ 385.00	\$ 385.00 x nn
8	1	Rear Bootlid Lock Striker	Serviceable	\$ 98.00	\$ -
9	1	Rear Bootlid Trim	Torned	\$ 596.00	\$ 596.00 x nn
10	2	Rear Bootlid Hinges	Bent	\$ 320.00	\$ 320.00 x nn
11	1	Rear Bootlid Weatherstrip	Deformed	\$ 388.00	\$ 388.00 /
12	1	Rear RHS Fender	Buckled	\$ 1,554.00	\$ 1,554.00 x R
13	1	Rear Windscreen Moulding	Necessary	\$ 420.00	\$ 420.00 x nn
14	1	Rear RHS Taillamp	Cracked	\$ 920.00	\$ 920.00 /
15	1	Rear RHS Taillamp Panel	Dented	\$ 388.00	\$ 388.00 x R
16	1	Rear RHS Taillamp Lower Bracket	Cracked	\$ 165.00	\$ 165.00 /
17	1	Rear Bumper	Cracked	\$ 1,088.00	\$ 1,088.00 590 /
18	2	Rear Bumper Retainer	Necessary	\$ 280.00	\$ 280.00 220 /
19	2	Rear Bumper Bracket	RHS Dent/ LHS Serviceable	\$ 320.00	\$ 160.00 x nn
20	1	Rear RHS Bumper End Shield	Deformed	\$ 165.00	\$ 165.00 x nn
21	1	Rear End Panel	Dented	\$ 988.00	\$ 988.00 689 /
22	1	Rear End Panel Top Garnish	Deformed	\$ 340.00	\$ 340.00 x nn
23	1	Rear RHS Fender Inner Trimboard	Deformed	\$ 699.00	\$ 699.00 x nn
24	1	Rear Spare Tyre Top Board	Deformed	\$ 550.00	\$ 550.00 x nn
25	1	Rear Spare Tyre Panel	Repair	\$ 1,408.00	\$ -
26	1	Rear Exhaust Gasket	Necessary	\$ 50.00	\$ 50.00 x nn
27	1	Rear Exhaust Silencer	Dented	\$ 1,380.00	\$ 1,380.00 x nn
28	1	Rear Exhaust Heat Shield	Serviceable	\$ 440.00	\$ -
29	2	Rear Exhaust Mounting	Necessary	\$ 200.00	\$ 200.00 x nn
Sub-total				\$ 15,339.80	\$ 12,613.90
Less 25%				\$ 3,834.95	\$ 3,153.48
Total				\$ 11,504.85	\$ 9,460.43

SL Auto Consultants

Accident Claims . Survey Services . Professional Advice

Add: 129 Lorong Ah Soo #05-352 Singapore S30129

Email: slautoconsultants@gmail.com / Mobile No: 90067276

SPECIAL NETT

1	1	Reverse Camera	Serviceable	\$	500.00	\$	-	
2	1	Reverse Sensor	Shorted	\$	400.00	\$	300.00	200
3		Set Rear Bumper Clip	Necessary	\$	100.00	\$	60.00	30
4		Set Rear Bootlid Trim Clip	Necessary	\$	100.00	\$	60.00	x nn
5		Set Rear End Panel Top Garnish Clip	Necessary	\$	100.00	\$	50.00	x nn
6		Set Fender Inner Trim Clip	Necessary	\$	100.00	\$	50.00	x nn
7	1	Taillamp Clip	Necessary	\$	100.00	\$	50.00	x nn
8	1	Windscreen Sealant	Necessary	\$	200.00	\$	100.00	x nn
Sub-total				\$	1,600.00	\$	670.00	

LABOUR

1	To check wiring and lighting	\$	100.00	\$	60.00	30
2	To remove and replace rear reserve sensor	\$	180.00	\$	80.00	30
3	To remove and refix rear reverse camera	\$	200.00	\$	100.00	50
4	To conduct water seepage test	\$	120.00	\$	60.00	x
5	To transfer rear bootlid mechanism from old to new	\$	240.00	\$	120.00	50
6	To remove and replace rear exhaust silencer	\$	240.00	\$	120.00	x
7	To remove and refix rear windscreen assy	\$	300.00	\$	240.00	x
8	To apply anti-rust proofing on affected areas	\$	300.00	\$	120.00	30
9	To remove and refix rear upholstery and to assist repair	\$	300.00	\$	160.00	50
10	To panel beat and replace damaged parts on affected areas	\$	2,500.00	\$	1,500.00	900
11	To putty and spray painting on affected areas	\$	2,500.00	\$	1,500.00	1000
Sub-total		\$	6,980.00	\$	4,060.00	
Total cost		\$	20,084.85	\$	14,190.43	

7 days