

OFFICIAL RECEIPT

No.: TC32023 10103

Date: 21/10/2023

Received from Lye Huitai

the sum of Dollars Two thousand only.

in payment of SKV8283 X Assessment Report Fees

\$ 2,000

Cash / Cheque No.:





# T & C AUTOMOBILE ASSESSORS

## TAX INVOICE

168 Auto Services Pte Ltd  
176 Sin Ming Drive #05-14  
Sin Ming Autocare  
Singapore 575721  
On Behalf Of  
LYE HUILAI

INV NO : TC3202310103

Date : 31/10/2023

### DESCRIPTION

### AMOUNT

Survey Fees  
(Including photographs and transport charges)

S\$  
2,000.00

---

2,000.00

---

VEHICLE NO : SKV8383X  
JOB REFERENCE NO : TC/3/2023/10103  
ACCIDENT DATE : 29/09/2023  
SURVEY DATE : 03/10/2023

T&C AUTOMOBILE ASSESSORS





# T & C AUTOMOBILE ASSESSORS

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No : SKV8383X

Report No : TC/3/2023/10103

### PANEL & MECHANICAL LABOUR

<u>S/NO</u>	<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
1	To remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	1,500.00	1,500.00
2	To check wiring and lightning for front headlamp.	300.00	250.00
3	To remove and install front sensor and reverse sensor.	300.00	250.00
4	To reprogram rear blind spot sensor, and perform function test.	500.00	400.00
5	To remove and install front right wheel rim, to repair and spray.	1,000.00	1,000.00
<b>Total :</b>		<u>3,600.00</u>	<u>3,400.00</u>



# T & C AUTOMOBILE ASSESSORS

## ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No : SKV8383X

Report No : TC/3/2023/10103

### PAINT

Code : TWO COAT METALLIC

#### LABOUR COST - PAINT

<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
To applies body filler , sanding , applies primer coat , spray painting and clearcoat. And polish the affected portions.	1,000.00	900.00
<b>Total :</b>	<b>1,000.00</b>	<b>900.00</b>

#### MATERIAL COST - PAINT

<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
To supplies polyurethane paint, clear coat lacquer, primer, masking tape, cleaning solvent, 1200- and 2000-grit sandpaper, filler, and paint thinner.	500.00	400.00
<b>Total :</b>	<b>500.00</b>	<b>400.00</b>

### FINAL CALCULATION

<u>DESCRIPTION</u>	<u>REPAIRER'S ESTIMATES S\$</u>	<u>OUR ASSESSMENT S\$</u>
Parts	14,214.51	14,214.51
Miscellaneous items	13,200.00	2,700.00
Panel & Mechanical Labour	3,600.00	3,400.00
Paint Labour	1,000.00	900.00
Paint Material	500.00	400.00
<b>Total Repair Cost :</b>	<b>32,514.51</b>	<b>21,614.51</b>

### Remarks

The repairer has agreed to undertake the repair of S\$ 21,614.51 , with a repair period of 5 working days .

Surveyed By :

Chan Kai Hua

