

ESTIMATE

8/11/2024

China Taiping Insurance (Singapore) Pte. Ltd
83 Anson Road #15-00
Springleaf Tower Singapore 079909

Vehicle No: SLJ2465J
Vehicle Model: AUDI A6
Est No: CBMQ24110113
Claims ref:
Accident Date: 08/11/24
In Charge: JUNIOR
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	FRONT BUMPER X	1	PC \$ 2,700.00	\$ 2,700.00 X
2	FRONT BUMPER RETAINER LH X	1	PC \$ 340.00	\$ 340.00 X
3	FRONT BUMPER CLIPS X	10	PC \$ 8.00	\$ 80.00 X
4	FRONT FENDER LH LH	1	PC \$ 1,680.00	\$ 1,680.00 1560
5	FRONT FENDER INNER SHIELD CLIPS m	10	PC \$ 8.00	\$ 80.00 40
6	FRONT FENDER INNER SHIELD de	1	PC \$ 310.00	\$ 310.00 260
7	FRONT DOOR LH requir	1	PC \$ 3,700.00	\$ 3,700.00 XR
8	REAR DOOR LH - REPAIR X	1	PC	\$ - X
9	SIDE SKIRT LH - REPAIR X	1	PC	\$ - X
10	FRONT DOOR OUTER HANDLE LH requir	1	PC \$ 690.00	\$ 690.00 537
11	SIDE MIRROR ASSY LH X	1	PC \$ 1,680.00	\$ 1,680.00 X
12	SIDE MIRROR COVER LH requir	1	PC \$ 390.00	\$ 390.00 137.15
13	SIDE MIRROR SIGNAL LIGHT LH requir	1	PC \$ 200.00	\$ 200.00 115.50
14	SIDE MIRROR HOUSING COVER LH de	1	PC \$ 360.00	\$ 360.00 148
15	SIDE MIRROR GLASS LH X	1	PC \$ 1,280.00	\$ 1,280.00 X
16	FRONT DOOR CHROME MOULDING LH X	1	PC \$ 500.00	\$ 500.00 X
17	REAR DOOR OUTER HANDLE LH X	1	PC \$ 690.00	\$ 690.00 X
18	REAR FENDER LH - REPAIR X	1	PC	\$ -
19	REAR BUMPER - REPAIR X	1	PC	\$ -
LIST TOTAL S\$				2797.65 5% \$ 14,680.00
5% DISCOUNT S\$				\$ (734.00)
				<u>\$ 13,946.00</u>

SPECIAL NET ITEMS:				
1	FRONT TYRE RIM LH requir	1	PC \$ 780.00	\$ 780.00 400
2	FRONT TYRE LH X	1	PC \$ 280.00	\$ 280.00 X
SPECIAL NET TOTAL S\$				<u>\$ 1,060.00</u>

LABOUR CHARGE:				
1	TO CUT, WELD, PANEL BEAT, STRAIGHTEN, REPLACE DAMAGED PARTS & REALIGN AFFECTED AREAS			500 \$ 1,200.00

ESTIMATE

8/11/2024

China Taiping Insurance (Singapore) Pte. Ltd
83 Anson Road #15-00
Springleaf Tower Singapore 079909

Vehicle No: SLJ2465J
Vehicle Model: AUDI A6
Est No: CBMQ24110113
Claims ref:
Accident Date: 08/11/24
In Charge: JUNIOR
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
2	TO PUTTY SPRAY PAINT ON FRONT BUMPER, FRONT FENDER LH, FRONT DOOR LH, REAR DOOR LH, A-PILLAR LH, B-PILLAR LH, SIDE SKIRT LH, REAR FENDER LH, REAR BUMPER, SIDE MIRROR COVER LH.			\$ 1,800.00 600
3	TO REMOVE & REFIT FRONT DOOR MECHANISM & OTHER ATTACHMENT PARTS			\$ 150.00 X
4	TO RUST PROOF ON A-PILLAR LH, B-PILLAR LH, SIDE PANE LH, REAR FENDER LH.			\$ 200.00 40
5	TO CHECK STEERING GEOMETRY & CONDUCT WHEEL ALIGNMENT		1360	\$ 100.00 70
6	TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM			\$ 280.00 150
TOTAL LABOUR COST S\$				\$ 3,730.00

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

AMOUNT S\$ \$ 18,736.00
GST @ 9% \$ 1,686.24
AMOUNT DUE S\$ \$ 20,422.24

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2657.76
400.00
1360.00
4417.76
20%
3534.21
43-\$3,500

Rasul
Hp 9001068
5 days
4/3
25/11/24
Res after repair

60SAFE