

# SkyCam Automobile Surveyor Services

(Registration no:52814962L)

Email: sim@skycam.com.sg/ Mobile: 65-97422188

63 Sims Place #13-207 Singapore 380063

Ng Hui Ting Jennifer Blk 21 I, Pasir Ris Street 21, #03-240 Singapore 510211	Invoice No: Date:	010323 14/03/2023
Description	Unit Price	Amount
Our Reference: <b>TP/01/03/23</b> Accident Date: <b>04/01/2023</b> Re: Survey fee/Photographs/Transport for: <b>SGU5502S</b> Workshop Name: <b>Power Build Technology</b> <b>Engineering Services</b> <b>25, Mandai Estate (Tower1) #02-07</b> <b>Innovation Place Singapore 729930</b>	\$ 2,800.00	\$ 2,800.00
		\$ 2,800.00

All payments by cheque should be crossed and make payable to

Skycam Automobile Surveyor Services

We thank you for your prompt payment

S.T.Sim



# SkyCam Automobile Surveyor Services

(Registration no:52814962L)

Email: sim@skycam.com.sg/ Mobile: 65-97422188

63 Sims Place #1 3-207 Singapore 380063

## Accident Car Inspection Report

**Ng Hui Ting Jennifer**  
**Blk 211, Pasir Ris Street 21,**  
**#03-240 Singapore 510211**

General Information			
Accident Date	04/01/2023	Type Survey	3rd Party Survey
Our Reference	TP/01/03/23	Date Survey	27/01/2023
Vehicle Details			
Vehicle No	<b>SGU5502S</b>	Registration Date	31/03/2017
Chassis No	MMBSTA13AHHH0047 31	Odometer	76151 km
Engine No	3A92UDT3626	Make	Mitsubishi Attrage
Engine Capacity	1193 cc	Model	1.2 CVT
Transmission Type	Auto	Colour	White
Tyres Condition			
Front: 5mm (195/55R15) PROXES Rear: 5mm (195/55R15) PROXES			
Repairer Name			
<b>Power Build Technology Engineering</b> <b>Services 25, Mandai Estate (Tower1)</b> <b>#02-07 Innovation Place Singapore</b> <b>729930</b>			
Comments/Instructions/General Damages			
<b>Damage to the rear, R/R end/F/R end, Front and rear suspension parts</b>			
We have further adjusted the amount to a lump sum contract of: <b>\$67,330.60</b> which is being deemed fair and reasonable. Under normal circumstances, the repairs period would take around <b>(21) working days</b> . We have <b>not authorised repairs</b> . This survey was conducted on " <b>Without Prejudice</b> " basis			

### Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicle and/or other accident in order legal proceedings.

**S.T.Sim**

Licensed Motor Surveyor

Diploma Vehicle Engineering (U.K)



# SkyCam Automobile Surveyor Services

(Registration no:52814962L)

Email: sim@skycam.com.sg/ Mobile: 65-97422188

63 Sims Place #1 3-207 Singapore 380063

Vehicle No: SGU5502S

Nature of Work and Materials	Repairers Estimate (\$)	Remarks	Revised Amount (\$)
Rear bumper	\$ 1,645.02	Bent	\$ 1,645.02 751 /
Rear bumper RH bracket	\$ 41.68	Distorted	\$ 41.68 /
Rear bumper reverse sensor	\$ 300.00	Bent	\$ 300.00 200 /
R/R trunk room trim garnish	\$ 365.90	Bent	\$ 365.90 x nn
Rear end panel top garnish	\$ 160.00	Bent	\$ 160.00 x nn
Rear trunk spare tyre top cover	\$ 1,200.00	Bent	\$ 1,200.00 x nn
Rear centre shelf trim top cover	\$ 588.00	Twisted	\$ 588.00 x nn
Rear boot partition luggage board	\$ 295.00	Twisted	\$ 295.00 x nn
R/R pillar upper trim garnish	\$ 152.00	Twisted	\$ 152.00 /
R/R quarter lower trim garnish	\$ 126.00	Twisted	\$ 126.00 x nn
Center pillar RH upper trim cover	\$ 89.00	Bent	\$ 89.00 x nn
Roof lining	\$ 1,047.00	Bent	\$ 1,047.00 548 /
Mitsubishi Emblem	\$ 102.00	Necessary	\$ 102.00 /
Attrage Logo	\$ 32.00	Distorted	\$ 32.00 /
R/R door outer handle	\$ 176.00	Distorted	\$ 176.00 /
R/R door trim board	\$ 423.00	Necessary	\$ 423.00 x nn
R/R door outer moulding	\$ 85.00	Necessary	\$ 85.00 /
R/R door weatherrstrip	\$ 234.00	Necessary	\$ 234.00 185 /
R/R side rocker drip moulding	\$ 144.00	Bent	\$ 144.00 x nn
R/R door latch	\$ 552.00	Bent	\$ 552.00 x nn
R/R door striker	\$ 34.00	Distorted	\$ 34.00 x nn
Total Amount Revised	\$7,791.60		\$7,791.60
Nett Total Approved			\$7,791.60
It is estimated that the repairs will take 21 working days to complete			



# SkyCam Automobile Surveyor Services

(Registration no:52814962L)

Email: sim@skycam.com.sg/ Mobile: 65-97422188

63 Sims Place #I 3-207 Singapore 380063

Vehicle No: SGU5502S

Nature of Work and Materials	Repairers Estimate (\$)	Remarks	Revised Amount (\$)
R/R door power window motor	\$671.00	Bent	\$671.00 x nn
R/R door window regulator	\$225.00	Bent	\$225.00 x nn
R/R door assy	\$1,506.00	Dented	\$1,506.00 976 /
R/R door outer moulding	\$19.00	Bent	\$19.00 x nn
FIR door assy	\$1,699.00	Bent	\$1,699.00 950 /
FIR door weatherstrip	\$300.00	Deformed	\$300.00 x nn
FIR door glass run channel	\$33.00	Deformed	\$33.00 x nn
FIR door glass	\$509.00	Scratch	\$509.00 x nn
RIR door glass	\$306.00	Cracked	\$306.00 x nn
FIR door outer mirror cover	\$232.00	Cracked	\$232.00 116 /
FIR door outer mirror assy	\$1,240.00	Cracked	\$1,240.00 x nn
FIR door outer mirror holder	\$76.00	Cracked	\$76.00 x nn
FIR door latch	\$558.00	Bent	\$558.00 x nn
FIR door striker	\$34.00	Bent	\$34.00 x nn
FIR door outer handle	\$175.00	Bent	\$175.00 /
F/R door power window motor	\$665.00	Bent	\$665.00 x nn
FIR door window regulator	\$231.00	Bent	\$231.00 x nn
FIR fender inner liner	\$168.00	Distorted	\$168.00 /
FIR fender	\$750.00	Crushed	\$750.00 438 /
Rear boot	\$1,531.00	Bent	\$1,531.00 828 /
Rear boot weatherstrip	\$273.00	Deformed	\$273.00 x nn
Rear boot RH hinge	\$347.00	Bent	\$347.00 x nn
Rear boot LH hinge	\$347.00	Bent	\$347.00 x nn
Rear boot latch assy	\$373.00	Bent	\$373.00 x nn
Rear boot striker	\$34.00	Bent	\$34.00 x nn
	\$12,302.00		\$12,302.00
Total Amount Revised			\$20,093.60
Nett Total Approved			\$20,093.60
It is estimated that the repairs will take 21 working days to complete			



# SkyCam Automobile Surveyor Services

(Registration no:52814962L)

Email: sim@skycam.com.sg/ Mobile: 65-97422188

63 Sims Place #1 3-207 Singapore 380063

Vehicle No: SGU5502S

Nature of Work and Materials	Repairers Estimate (\$)	Remarks	Revised Amount (\$)
Rear windscreen	\$1,100.00	Cracked	\$1,100.00
RIR fender	\$1,300.00	Crushed	\$1,300.00
RIR fender inner liner	\$60.00	Deformed	\$60.00
Roof panel RIR side reinforcement	\$320.00	Distorted	\$320.00
RIR pillar reinforcement	\$216.00	Distorted	\$216.00
RIR fender inner lower panel	\$392.00	Distorted	\$392.00
RIR wheel house inner panel	\$282.00	Distorted	\$282.00
RIR pillar inner panel	\$444.00	Distorted	\$444.00
RIR pillar self panel	\$120.00	Distorted	\$120.00
Rear center self panel	\$377.00	Distorted	\$377.00
Front windscreen	\$1,900.00	Scratch	\$1,900.00
Front bumper reinforcement	\$821.00	Bent	\$821.00
Front bumper assy	\$1,320.00	Bent	\$1,320.00
Front bumper lower grille	\$250.00	Bent	\$250.00
Front bumper RH garnish	\$192.00	Bent	\$192.00
Front bumper LH garnish	\$192.00	Bent	\$192.00
Front bumper RH tow cover	\$20.00	Missing	\$20.00
Front bumper LH tow cover	\$20.00	Missing	\$20.00
FIR fender	\$750.00	Bent	\$750.00
FIR fender inner liner	\$120.00	Bent	\$120.00
Radiator grille	\$824.00	Cracked	\$824.00
FIR headlamp assy	\$1,066.00	Cracked	\$1,066.00
FIL headlamp assy	\$1,066.00	Cracked	\$1,066.00
RIR tail lamp assy	\$550.00	Cracked	\$550.00
Rear 3rd brake mount light		Cracked	
	\$13,952.00		\$13,952.00
Total Amount Revised			\$34,045.60
Nett Total Approved			\$34,045.60
It is estimated that the repairs will take 21 working days to complete			



# SkyCam Automobile Surveyor Services

(Registration no:52814962L)

Email: sim@skycam.com.sg/ Mobile: 65-97422188

63 Sims Place #I 3-207 Singapore 380063

Vehicle No: SGU5502S

Nature of Work and Materials	Repairers Estimate (\$)	Remarks	Revised Amount (\$)	
Rear axle member	\$1,972.00	Twisted	\$1,972.00	x nn
RIR shock absorber	\$318.00	Bent	\$318.00	x nn
RIR shock absorber damper	\$48.00	Bent	\$48.00	x nn
RIL shock absorber	\$318.00	Bent	\$318.00	x nn
RIL shock absorber damper	\$48.00	Bent	\$48.00	x nn
Front crossmember	\$1,680.00	Twisted	\$1,680.00	x nn
FIR lower arm	\$421.00	Twisted	\$421.00	x nn
FIL lower arm	\$421.00	Twisted	\$421.00	x nn
Front stabiliser link	\$483.00	Twisted	\$483.00	x nn
FIL strut assy	\$772.00	Bent	\$772.00	x nn
FIR strut assy	\$772.00	Bent	\$772.00	x nn
FIR drive shaft assy	\$2,567.00	Twisted	\$2,567.00	x nn
FIL drive shaft assy	\$2,567.00	Twisted	\$2,567.00	x nn
FIR steering Knuckle	\$643.00	Twisted	\$643.00	x nn
FIL steering Knuckle	\$643.00	Twisted	\$643.00	x nn
FIR wheel hub	\$408.00	Bent	\$408.00	x nn
FIL wheel hub	\$408.00	Bent	\$408.00	x nn
FIR wheel hub bearing	\$208.00	Necessary	\$208.00	x nn
FIL wheel hub bearing	\$208.00	Necessary	\$208.00	x nn
Steering rack & pinion assy	\$3,080.00	Twisted	\$3,080.00	x nn
	\$17,985.00		\$17,985.00	
Total Amount Revised			\$52,030.60	
Nett Total Approved			\$52,030.60	
It is estimated that the repairs will take 21 working days to complete				



# SkyCam Automobile Surveyor Services

(Registration no:52814962L)

Email: sim@skycam.com.sg/ Mobile: 65-97422188

63 Sims Place #I 3-207 Singapore 380063

Vehicle No: SGU5502S | Model: Mitsubishi Attrage 1.2 CVT

## A. Labour Charge

Sino	Job Description	Repairer's Estimate	Revised Estimate	
1	To labour charge for removing rear boot and rear bumper and end panel inner and outer etc straighten front support panel front bumper, out to facilitate repairs and replacement of damaged parts	\$ 6,500.00	\$ 6,000.00	1800
2	To respray rear boot inner and outer, rear bumper, end panel inner and outer, roof top panel, R/R fender, F/R fender, Front bonnet, R/R door, F/R door, rear bumper and front bumper	\$ 4,000.00	\$ 3,800.00	1600
3	To labour charge to remove and replace reverse sensors	\$ 400.00	\$ 300.00	30
4	To labour charge for removing and installing front and rear windscreen out for replacement of parts	\$ 600.00	\$ 600.00	240
	<b>Total Labour (A)</b>	\$ 11,500.00	\$ 10,700.00	
	<b>C/F</b>			



# SkyCam Automobile Surveyor Services

(Registration no:52814962L)

Email: sim@skycam.com.sg/ Mobile: 65-97422188

63 Sims Place #I 3-207 Singapore 380063

**Vehicle No: SGU5502S Model: Mitsubishi Attrage 1.2 CVT**

## B. Labour Charge

Sino	Job Description	Repairer's Estimate	Revised Estimate	
5	To labour charge for removing out rear suspension parts out to facilitate replacement of damaged parts	\$ 900.00	\$ 800.00	x
6	To labour charge for removing out front suspension parts out to facilitate replacement of damaged parts	\$ 900.00	\$ 800.00	x
7	To conduct 4 post wheel alignment	\$ 450.00	\$ 300.00	80
8	Towing fee (2 trips) (King Dolly)	\$ 500.00	\$ 500.00	100
9	To supply <sup>2</sup> 4 pcs road wheels rims (S/Nett)	\$ 1,200.00	\$ 1,200.00	800
10	To supply <sup>2</sup> 4 pcs tires (S/Nett) (Front RH) (rear RH)	\$ 1,000.00	\$ 1,000.00	210
				150 x 2 (- depreciation 30%) = 105
	<b>Total Labour (B)</b>	\$ 4,950.00	\$ 4,600.00	
	<b>Grand Total Labour (A+B)</b>	\$ 16,450.00	\$ 15,300.00	
	<b>Grand Total Parts &amp; Labour</b>	\$ 68,480.60	\$ 67,330.60	

12 days