

YEE KEONG MOTOR ENGINEERING

No 14 Penjuru Road, Singapore 609125
 EMAIL yeekeongmotorengineering@gmail.com
 MOBILE 97808928

Est Reg No Xe 93582@Trc 6966 v

Date 22/11/24

- 1 Supply new bumper 1/pc 4 ✓
- 2 Labour to conduct hotworks to remove damaged bumper & install new
- 3 Supply new number plate lamp
- 4 To provide materials to fabricate new RHS rear lamp bracket
- 5 Labour to remove damaged lamp bracket & weld on new
- 6 RHS rear twistlock bracket repair and welding work
- 7 Labour to replace damaged no plate lamp & wiring work
- 8 Red reflective 20&20 RM ✓
- 9 3M reflective sticker 20&20 RM ✓
- 10 50 kmh marker RM ✓
- 11 Supply new RHS rear mudguard rear trailer thermoplastic mudguard & mudflap set c/w replacement works
- 12 Localised spray paint works for rear of trailer

Special
nett

1040

850

labour

~~\$800.00~~ 500
~~\$450.00~~ 350
~~\$50.00~~ X 111
~~\$80.00~~ 40
~~\$150.00~~ 80
~~\$150.00~~ X 111
~~\$120.00~~ X 111
~~\$40.00~~ 30
~~\$40.00~~ 30
~~\$20.00~~ 10

~~\$600.00~~ 400
~~\$550.00~~ 450

TOTAL \$3050 00

Rasul
 4p 20010368
 4 days
 45
 15/11/24
 Reg after repair

45- \$1500 / 4 days 1040
 850
 1890
 20%
 1512

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: