



辉皇鸿寶

# HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921

Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhb.com.sg

Company Reg. No. 202341776E

Vehicle No.: SLX6864R  
Make/Model : Honda Vezel 1.5X  
Chassis no.: RU31267092  
Year of Manufacture : 2017

Date of survey:  
Surveyor:  
Company :  
Ins Company : Income  
TP vehicle No.: SLF9332J

TP INC.

Xiao Chen.

Accident Date : 14 Nov 2024

Type of repair: Lump Sum

## Estimate cost of repairs

| Qty  | Part Description                        | Unit Price  | Total Price     |
|------|-----------------------------------------|-------------|-----------------|
| 1 pc | Tailgate <i>Dented</i>                  | \$ 1,100.90 | \$ 1,100.90 ✓   |
| 1 pc | Tailgate 'H' emblem <i>new</i>          | \$ 33.10    | \$ 33.10 +      |
| 1 pc | Tailgate 'Vezel' emblem <i>3/4</i>      | \$ 70.50    | \$ 70.50 ✓      |
| 1 pc | Tailgate 'Hybrid' emblem <i>3/4</i>     | \$ 66.20    | \$ 66.20 ✓      |
| 1 pc | Tailgate inner trimboard <i>3/4 new</i> | \$ 225.30   | \$ 225.30 ✓     |
| 1 pc | Tailgate weatherstrip <i>new</i>        | \$ 95.00    | \$ 95.00 ✓      |
| 1 pc | Rear windscreen moulding <i>new</i>     | \$ 158.60   | \$ 158.60 ✓     |
| 1 pc | Rear bumper <i>Dented</i>               | \$ 863.50   | \$ 863.50 ✓ 745 |
| 1 pc | Rear end panel top garnish <i>new</i>   | \$ 86.00    | \$ 86.00 ✓      |

Less 20%

2141.20  
1712.96

\$ 2,699.10  
\$ (539.82)  
\$ 2,159.28

|       |                                         |                        |
|-------|-----------------------------------------|------------------------|
| 1 set | Reverse sensor <i>Dented</i>            | \$ 250.00 SN <i>2w</i> |
| 1 set | Rear bumper clips <i>new</i>            | \$ 50.00 SN <i>30</i>  |
| 1 set | Tailgate trimboard clips <i>3/4 new</i> | \$ 50.00 SN <i>2</i>   |
| 1 set | Rear windscreen sealant <i>new</i>      | \$ 50.00 SN ✓          |
|       |                                         | \$ 400.00              |

280

|       |                                         |                     |
|-------|-----------------------------------------|---------------------|
| 1 job | To putty and spray painting             | \$ 600.00 <i>4w</i> |
| 1 job | Wiring Charges                          | \$ 60.00 <i>30</i>  |
| 1 job | To remove & refit rear windscreen glass | \$ 120.00 ✓         |
| 1 job | To remove & renew reverse sensors       | \$ 80.00 <i>50</i>  |
| 1 job | To remove & refit back-up camera        | \$ 80.00 <i>50</i>  |



辉皇鸿寶

## HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921  
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhb.com.sg  
Company Reg. No. 202341776E

1 job To remove & refit tailgate interior fittings

\$ ~~150.00~~ 60.

1 job Labour to remove rear accident damaged parts in order to repairs including panel beat and replace above parts.

\$ ~~800.00~~ 500

8210

\$ 1,890.00

Grand-total

\$ 4,449.28

Admin  
2/S 15/11/24  
04 Days

Supplementary: 40032  
Total: 3603.28,  
2/S: 2850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



辉皇鸿寶

# HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921  
Office: 6844 7414 | Fax: 6844 7401 | Email: c'aims@hhbhm.com.sg  
Company Reg. No. 202341 76E

Vehicle No.: SLX6864R

Make/Model : Honda Vezel 1.5X

Chassis no.: RU31267092

Year of Manufacture : 2017

Date of survey: 15 Nov 2024

Surveyor: Adrian

Company : LKK

Ins Company : Income

TP vehicle No.: SLF9332J

Accident Date : 14 Nov 2024

Type of repair: Lump Sum

## Supplementary

| Qty   | Part Description                                                                                               | Unit Price | Total Price |      |
|-------|----------------------------------------------------------------------------------------------------------------|------------|-------------|------|
| 1 pc  | Rear buzzer <i>changed</i>                                                                                     | \$ 87.90   | \$ 87.90    | ✓    |
| 1 pc  | Rear end panel <i>Repairs</i>                                                                                  | \$ 601.60  | \$ 601.60   | X    |
|       |                                                                                                                |            | \$ 689.50   |      |
|       | Less 20%                                                                                                       |            | \$ (137.90) |      |
|       |                                                                                                                |            | \$ 551.60   |      |
| 1 set | Rear end panel sealant <i>the new</i>                                                                          | \$ 60.00   | \$ 60.00    | SN X |
| 1 job | To putty and spray painting                                                                                    | \$ 200.00  | \$ 200.00   | 200  |
| 1 job | Tuff coat                                                                                                      | \$ 60.00   | \$ 60.00    | 30   |
| 1 job | Labour to remove rear accident damaged parts in order to repairs including panel beat and replace above parts. | \$ 400.00  | \$ 400.00   | 100  |
|       |                                                                                                                |            | \$ 660.00   |      |

87.90

70.32

330

Supplementary : 400.32