



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: c'aims@hhbhm.com.sg
Company Reg. No. 202341 76E

Vehicle No.: SLX6864R

Make/Model : Honda Vezel 1.5X

Chassis no.: RU31267092

Year of Manufacture : 2017

Date of survey: 15 Nov 2024

Surveyor: Adrian

Company : LKK

Ins Company : Income

TP vehicle No.: SLF9332J

Accident Date : 14 Nov 2024

Type of repair: Lump Sum

Supplementary

Qty	Part Description	Unit Price	Total Price	
1 pc	Rear buzzer <i>changed</i>	\$ 87.90	\$ 87.90	✓
1 pc	Rear end panel <i>Repairs</i>	\$ 601.60	\$ 601.60	X
			\$ 689.50	
	Less 20%		\$ (137.90)	
			\$ 551.60	
1 set	Rear end panel sealant <i>the new</i>	\$ 60.00	\$ 60.00	SN X
1 job	To putty and spray painting	\$ 200.00	\$ 200.00	200
1 job	Tuff coat	\$ 60.00	\$ 60.00	30
1 job	Labour to remove rear accident damaged parts in order to repairs including panel beat and replace above parts.	\$ 400.00	\$ 400.00	100
			\$ 660.00	

87.90

70.32

330

Supplementary : 400.32