

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CHONG SAN MING
BLK 773 YISHUN AVE 3 #09-173
SINGAPORE 760773

Contact : 96193677

TP/NC
vercon.
TAX INVOICE

Repair Code : CLM18458
Date in : 14/11/2024
Vehicle Num. : SMD3138S
Model : TOYOTA LEXUS NX300 LUXURY S/R
Chassis/Eng# : JTJBARBZ702176079/8ARW815814

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount	1505
FRONT BUMPER <i>Delid</i>	1	1630.80	1,630.80	<i>✓</i>
FRONT BUMPER INNER SIDE BRACKET LH <i>After could</i>	1	172.10	172.10	<i>✓</i>
FRONT BUMPER LH FOG LAMP GARNISH <i>new</i>	1	140.50	140.50	<i>+</i>
<i>x</i> FRONT BUMPER LH NOZZLE <i>new</i>	1	199.10	199.10	<i>+</i>
FRONT BUMPER LH NOZZLE BRACKET <i>After could</i>	1	71.30	71.30	<i>✓</i>
FRONT BUMPER LH PARKING SENSOR <i>new</i>	1	630.40	630.40	<i>+</i>
FRONT BUMPER LH PARKING SENSOR HOLDER <i>new</i>	1	51.00	51.00	<i>+</i>
FRONT BUMPER LH SIGNAL LAMP LED <i>cut</i>	1	2820.90	2,820.90	<i>1709</i>
FRONT BUMPER SIDE RETAINER L/R <i>2H could</i>	2	191.70	383.40	<i>191.70</i>
FRONT LH FENDER <i>Delid</i>	1	2182.70	2,182.70	<i>1290</i>
FRONT LH FENDER ARCH GARNISH <i>Delid</i>	1	313.50	313.50	<i>12480.57</i>
FRONT LH FENDER INNER SHIELD <i>new</i>	1	457.30	457.30	<i>+</i>
FRONT LH HEADLAMP <i>could</i>	1	8414.70	8,414.70	<i>+</i>
FRONT LH HEADLAMP LOWER BRACKET <i>2601 m</i>	1	305.80	305.80	<i>+</i>
Subtotal before discount			17,773.50	
Percentage discount 10%			1,777.35	
Sub-total 1			15,996.15	
FRONT BUMPER CLIPS - SET <i>new</i>	1	80.00	80.00	<i>30</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CHONG SAN MING
BLK 773 YISHUN AVE 3 #09-173
SINGAPORE 760773

TAX INVOICE

Repair Code : CLM18458

Date in : 14/11/2024

Vehicle Num. : SMD3138S

Model : TOYOTA LEXUS NX300 LUXURY S/R

Chassis/Eng# : JTJBARBZ702176079/8ARW815814

Contact : 96193677

FRONT LH FENDER ARCH GARNISH CLIPS - SET	1	40.00	40.00 30
FRONT LH FENDER INNER SHIELD CLIPS - SET	1	80.00	80.00 +
Subtotal before discount			200.00
Percentage discount 0%			0.00
Sub-total 2			200.00
Parts-total			16,196.15

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To reset system after repair works

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,980.00
Parts & Labour Total	18,176.15

*** This is a computer-generated document which requires no signature.***

page 2

- KK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

10.7K

Admin
L/S 15/11/24
04 Days
Tel: 13370-57
L/S: 10.7K.