

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2401781

INV Date : 10-12-2024

Reference CD/FCI24060276/Rma3q2

Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SNG 8913K
Insured Veh. SHD 4401J
Claim No. D24005504MFCT/CTPL/TPD-2
Policy No. D-24101861MFCT
Accident Date 21/06/2024
Inspection Date 26/06/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24060276/Rma3q2
16 RAFFLES QUAY	Date:	10/12/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHD 4401J	Veh. Inspected	SNG 8913K
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24005504MFCT/CTPL/TPD-2	Excess	\$0.00
Assign From	CHRIS LIM	Assign Date	25/06/2024

2. Vehicle Details

Make & Model	SUBARU XV 2.0I-S EYESIGHT AWD CVT	C.C	1995
Engine No.	FB20YP69302	Year of Reg.	13/05/2022
Chassis No.	JF1GT7KL5MG122593	Colour	BLUE
Odometer	45898 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55 R18	BRIDGESTONE	6
L/H Front Tyre	225/55 R18	BRIDGESTONE	6
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/06/2024	Inspection Date	26/06/2024
Survey held at	25 LENG KEE ROAD, SINGAPORE 159097		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNG 8913K

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	VALVE TPMS ASSY (SN)	NECESSARY	\$177.00	\$177.00
1	PNL COMPL DR R WRH (SN)	BENT	\$933.00	\$933.00
1	TAPE DR SASH R M WRH (SN)	NECESSARY	\$8.00	\$8.00
1	GARNISH AY SDSL RH (SN)	SCRATCHED	\$187.00	\$187.00
1	GARNISH AY R QTR RH (SN)	SCRATCHED	\$152.00	\$152.00
1	RIM GT EDTN 18 (SN)	SCRATCHED	\$1,553.00	\$1,553.00
1	SIDE UNDER SPOILER GT RH -ML (SN)	SCRATCHED	\$347.00	\$347.00
1	SUNDRIES (SN)	NECESSARY	\$100.00	\$20.00
1	RESPRAY REAR RHS QTR PANEL (SN) (ADDITIONAL)	NECESSARY	\$600.00	\$600.00
			\$4,057.00	\$3,977.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REPLACE REAR RHS DOOR ,RHS SIDE SKIRT ,QTR GARNISH AND WHEEL		\$3,000.00	\$1,360.00
	RESPRAY REAR RHS DOOR ASSY		\$2,000.00	\$600.00
	TO RMV,INSP & TRF RR DR PANEL & LOCK ,PWR WINDOW MOTOR & GLASS WIRE HAR & ETC TO NEW DOOR		\$260.00	\$260.00
	TO REMOVE & REPLACE ONE TIRE WITH BALANCING		\$50.00	\$50.00
	TO CARRY OUT COMPUTERIZED WHEEL ALIGNMENT INSP & ADJUST SUSPENSION SYSTEM		\$240.00	\$240.00
	CARRY OUT DIAGNOSTIC CHECKS & RESET SYSTEMS		\$320.00	\$320.00
	TO CARRY OUT SIDE GT BODY KIT INSTALLATION		\$250.00	\$250.00
			\$6,120.00	\$3,080.00

GRAND TOTAL			\$10,177.00	\$7,057.00
	RECOMMENDED COST OF REPAIRS			\$7,057.00

Report Ref No: CD/FCI24060276/Rma3q2

MRB

MOHAMMED RASUL BIN MOHD YUNUS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNG 8913K





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 2 of 6)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 8913K





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 6)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 8913K





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 6)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 8913K



PHOTOGRAPHS FOR VEHICLE NO. : SNG 8913K



PHOTOGRAPHS FOR VEHICLE NO. : SNG 8913K






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 8913K





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SNG 8913K

