



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIED WORLD ASSURANCE COMPANY LTD (SINGAPORE BRANCH) 60 ANSON ROAD #08-01 (8th FLOOR) MAPLETREE ANSON SINGAPORE 079914 ATTN: STELLA GOH			Ref: CS/AWA24110322/Rvp3e2(N) Date: 10/01/2025 Code: AWA	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	GBF 2166L	<b>Veh. Inspected</b>	SNN 6950D
	<b>Policy No.</b>	BVF2SB0002772403	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	CSG24VF2PA00019/HLF	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	STELLA GOH	<b>Assign Date</b>	15/11/2024
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA YARIS CROSS 1.5G	<b>c.c</b>	1490
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2023
	<b>Chassis No.</b>	MXPB103019531	<b>Colour</b>	BLUE
	<b>Odometer</b>	6893 KM	<b>Steering</b>	IN ORDER
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	205/65 R16	BRIDGESTONE	6 mm
	<b>L/H Front Tyre</b>	205/65 R16	BRIDGESTONE	6 mm
	<b>R/H Rear Tyre</b>	205/65 R16	BRIDGESTONE	6 mm
	<b>L/H Rear Tyre</b>	205/65 R16	BRIDGESTONE	6 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	13/11/2024	<b>Inspection Date</b>	15/11/2024
	<b>Survey held at</b>	MOVA AUTOMOTIVE PTE LTD 15 FAN YONG ROAD SINGAPORE 629792		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>7 Working Days</b>	