



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24110325/Uvh3m4
75 BRAS BASAH ROAD	Date:	05/12/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 2446L	Veh. Inspected	GBC 9484M
Policy No.	-	Coverage	0
Claim No.	MT/1303930-002	Excess	\$0.00
Assign From	RAJESWARY	Assign Date	15/11/2024

2. Vehicle Details

Make & Model	TOYOTA DYNA 150 MANUAL	C.C	2982
Engine No.	1KD2383086	Year of Reg.	25/03/2014
Chassis No.	JTFAT35Y20K202880	Colour	SILVER
Odometer	152299 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195R15	BRIDGESTONE	5
L/H Front Tyre	195R15	BRIDGESTONE	5
R/H Rear Tyre	155R12 (D)	YOKOHAMA	5/5
L/H Rear Tyre	155R12 (D)	YOKOHAMA	5/5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/11/2024	Inspection Date	19/11/2024 (09:13)
Survey held at	LLM AUTO LEASING PTE LTD C/O BLUWEL AUTOMOTIVE SERVICE PTE LTD - 1 KAKI BUKIT AVENUE 6 BLK C #01-56 SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days