

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24110326/DNP3E2
Date: 16/01/2025**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1002983256
Claimant Vehicle No :	FBR6083C	Insured Vehicle No :	SJK7448U
Date of Loss:	10/11/2024	Nature of Claim:	TP
		Claim No:	380553

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBR6083C	Engine No:	4S3001596
Make & Model:	YAMAHA X-1R, 134cc (M)	Chassis No:	4S3001596
Reg. Date:	09/11/2007 (Man. Year: 2007)	Odometer:	3854 km
Colour:	Red		
Engine Capacity:	135 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	70/90 R17	Rear Tyre Size:	70/90 R17
Front Left Side:	Maxxis 5 mm	Rear Left Side:	Maxxis 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,119.50	1,222.20	897.30	42.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	840.00	230.00	610.00	72.62
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,959.50	1,452.20	1,507.30	50.93
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	2,959.50	1,100.00	1,859.50	62.83
+ GST 9.00/9.00% (S\$)	266.36	99.00	167.36	62.83
Nett Amount (S\$)	3,225.86	1,199.00	2,026.86	62.83

INSPECTION

Date of Assignment:	18/11/2024	
Date Inspected:	18/11/2024	Inspected At: Yew Tee Automobile Tech Pte Ltd (Woodlands) 39 Woodlands Close #01-12, Mega@Woodlands Singapore 737856
Estimated Period of Repair:	3.0 days	

Adjuster: BRYAN TANI**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 16 Jan 2025)	
Parts:	N/A	YAMAHA X-1R 134cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR6083C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT SIDE MIRROR LH	Not Necessary	85.00 FL	*- FL
2	1		*FRONT CLUTCH LEVER LH	Cut	28.00 FL	*28.00 FL
3	1		*FRONT SIDE FAIRING LH	Cracked	380.00 FL	*330.00 FL
4	1		*FRONT SIDE FAIRING LOGO LH	Necessary	52.00 FL	*30.00 FL
5	1		*FRONT SIDE FAIRING LAMP LH	Cut	310.00 FL	*260.00 FL
6	1		*SET FRONT FORK	Not Necessary	420.00 FL	*- FL
7	1		*FRONT HANDLE BAR	Not Necessary	270.00 FL	*- FL
8	1		*FRONT HEADLAMP	Cracked	480.00 FL	*430.00 FL
9	1		*FRONT HEADLAMP FAIRING	Cracked	330.00 FL	*280.00 FL
					Sub Total (\$\$)	2,355.00 1,358.00
					- List Item Discount on L Items 10.00/10.00% (\$\$)	235.50 135.80
					Total Parts (\$\$)	2,119.50 1,222.20

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO ELECTRICAL WIRING SERVICES	New	30.00	30.00
2	TO DISMANTLE AND REFIT FRONT UNDERCARRIAGE	New	150.00	0.00
3	TO COMPUTER WHEEL ALIGNMENT	New	60.00	0.00
4	TO REMOVE, REFIX, REALIGN, ADJUST AND REPLACE ALL DAMAGED PARTS	New	350.00	200.00
5	TO UNDERCOATING FOR RUST PROTECTION	New	30.00	0.00
6	TO RESPRAY PAINT OF ACCIDENT SECTION	New	220.00	0.00
Gross Labour Cost (\$\$)			840.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >