

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Melvin Ye Yongkang

Date: 26 Nov 2024

Preliminary Advice

Insured Vehicle No	: SJK7448U		
TP Vehicle No	: FBR6083C	Accident Date	: 10/11/2024
Make	: YAMAHA X-1R	Assignment Date	: 18/11/2024
Date of Inspection	: 18/11/2024	Est. Duration of Repair	: 3
Inspection At	: YEW TEE AUTOMOBILE TECH PTE LTD (WOODLANDS) 39 WOODLANDS CLOSE #01-12, MEGA@WOODLANDS SINGAPORE 737856		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,959.50
Revised Amount	:S\$	1,832.00
Check Items (Estimated)	:S\$	120.00
Total	:S\$	1,952.00
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- (x) Part-by-Part repair
- () Lump Sum repair

- (x) The above survey was conducted on a 'without prejudice' basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.