

Not Notarised  
11 Nov 8 1550h

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF621G**

**AAD2410-075**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

21 NOV 2024

**SHF621G**

JTDB3FU203092063

200303878K

TOYOTA

PRIUS GEN 4

21/10/2024

**SKT6407K/** TH

12/3/2021

**PART**

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, FLOOR UNDER, NO.1 LH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK

**LIST**

\$	Bu	612.68	✓
\$	PA	419.90	✓
\$	nd	27.93	✓
\$	Del Cvt	472.19	✓
\$	SL	167.48	X
\$	SL	167.48	X
\$	SL	49.25	X
\$	SL	49.25	X
\$	SL	220.50	X
\$	SL	304.92	X
\$	CMA SL	290.43	✓
\$	SL	159.39	X
\$	n	824.46	X
<b>TOTAL \$</b>		<b>3,765.86</b>	
<b>25% \$</b>		<b>941.47</b>	
<b>\$</b>		<b>2,824.40</b>	

**Special Nett**

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR NO. PLATE
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR BUMPER RETAINER CLIP

\$	SL	700.00	X
\$	SL	95.00	60SL
\$	SL	150.00	X
\$	SL	200.00	X
\$	SL	130.00	X
\$	SL	180.00	X
\$	SL	180.00	30SL
\$	SL	250.00	X
\$	SL	85.00	X

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF621G**

1 END PANEL TRIM CLIP

**AAD2410-075**\$ *nn* 65.00 X**TOTAL \$ 2,035.00****TOTAL PARTS \$ 4,859.40****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ *nn* 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 *200l*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ *nn* 180.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ *nn* 250.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 *220l*

To reinstall rear bumper parking sensor.

\$ 170.00 *50l*

To Check Electrical Lighting Concerned.

\$ 170.00 *10l***TOTAL \$ 5,030.00****\$ 9,889.40**LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are (PART-BY-PART) Repair Days
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*04 DAYS**2 days*