

CARSMITH PRIVATE LIMITED
PREMIER@8 KAKI BUKIT AVE 4 #04-35 Singapore 415875
Tel: 9091 0000

Not Airland
no more
27/6/24
1/5 \$3300
Cheng Heng
4/5

VEHICLE NO: SLG6646T
MAKE & MODEL: HONDA STREAM
DOA: 25.06.2024
CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE <i>952</i>	1	\$ 1,423.00	<i>25/But</i>
TAILGATE INNER TRIM BOARD	1	\$ 390.00	<i>SLX</i>
TAILGATE WEATHERSTRIP	1	\$ 197.00	<i>Tw</i>
TAILGATE INNER LOCK	1	\$ 286.00	<i>Page</i>
TAILGATE DAMPER LH	1	\$ 231.00	<i>11 X</i>
TAILGATE DAMPER RH	1	\$ 231.00	<i>11 X</i>
TAILGATE LOGO	1	\$ 98.00	<i>11 X</i>
TAILGATE EMBLEM 'STREAM' <i>48.22</i>	1	\$ 95.00	<i>11</i>
TAILGATE OUTER GARNISH	1	\$ 393.10	<i>11 X</i>
TAILGATE INNER HANDLE GARNISH	1	\$ 78.00	<i>11 X</i>
TAILGATE WIPER MOTOR	1	\$ 485.00	<i>11 X</i>
TAILLAMP LH	1	\$ 690.60	<i>11 X</i>
TAILLAMP PANEL LH	1	\$ 204.60	<i>11 X</i>
TAILLAMP RH	1	\$ 690.60	<i>11 X</i>
TAILLAMP PANEL RH	1	\$ 204.60	<i>11 X</i>
REAR END PANEL <i>452</i>	1	\$ 910.00	<i>But</i>
REAR END PANEL TOP GARNISH	1	\$ 187.00	<i>11 X</i>
REAR EXHAUST COVER	1	\$ 195.00	<i>11 X</i>
REAR BUMPER <i>698</i>	1	\$ 1,530.00	<i>25</i>
REAR BUMPER SIDE RETAINER LH	1	\$ 120.20	<i>11 X</i>
REAR BUMPER SIDE RETAINER RH	1	\$ 120.20	<i>11 X</i>
REAR BUMPER BRACKET LH	1	\$ 98.00	<i>11 X</i>
REAR BUMPER BRACKET RH	1	\$ 98.00	<i>11 X</i>
REAR BUMPER SPONGE @ SGD 98	2	\$ 196.00	<i>NSX</i>
REAR BUMPER TOW COVER <i>30</i>	1	\$ 48.00	<i>NS</i>
REAR BUMPER REFLECTOR GARNISH LH	1	\$ 169.00	<i>NSX</i>
REAR BUMPER REFLECTOR GARNISH RH	1	\$ 169.00	<i>NSX</i>
REAR BUMPER REFLECTOR LH	1	\$ 145.00	<i>NSX</i>
REAR BUMPER REFLECTOR RH	1	\$ 145.00	<i>NSX</i>
		\$ 9,827.90	
	LESS 20%	\$ 1,965.58	
	SUB TOTAL	\$ 7,862.32	

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
TAILGATE WINDSCREEN SEALANT	1	\$ 100.00	<i>11 40</i>
TAILGATE INNER SEAL	1	\$ 50.00	<i>11 20</i>
TAILGATE SEALANT	1	\$ 100.00	<i>11 X</i>
TAILGATE TRIMBOARD CLIPS	1 SET	\$ 50.00	<i>11 X</i>
REAR NUMBER PLATE	1	\$ 80.00	<i>11 X</i>
REAR BUMPER CLIPS	1 SET	\$ 50.00	<i>11 30</i>
REAR END PANEL SEALANT	1	\$ 80.00	<i>11 X</i>

REAR END PANEL TOP GARNISH CLIPS	1 SET	\$ 50.00	MAX
REVERSE SENSOR W MOUDLE	1 set	\$ 300.00	malfunction 200
SUB TOTAL		\$ 860.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK REAR WIRING AND LIGHTING SYSTEM	1	\$ 100.00	20
TO REMOVE AND REFIT REAR TAILGATE GLASS TO FACILITATE THE REPAIR	1	\$ 200.00	120
TO REMOVE AND REFIT TAILGATE COMPONENT TO REPLACE TAILGATE, CHECK AND RE-ADJUST THE CLOSE GAP AND ALIGNMENT AND WATER SEEPAGE	1	\$ 100.00	60
TO REMOVE AND REFIT INTERIOR UPHOLSTERY TO FACILITATE THE REPAIR.	1	\$ 200.00	60
TO MEASURE, DRILLS HOLES ON REPLACED REAR BUMPER, POSITION AND INSTALL REVERSE SENSOR, CHECK AND TEST ON THE DISTANCE AND FUNCTIONS	1	\$ 80.00	30
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,400.00	600
SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,400.00	800
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	50

SUB TOTAL \$ 3,580.00

GRAND TOTAL \$ 12,302.32

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

p. 2604
207
2/31-20
290
1740
41612
202
3322