

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
as
19/11/24
2/s \$1400/
Telephone
2 days

18 November 2024

REG NO. : YP4828Y
MAKE/MODEL : MITSUBISHI CANTER

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Front Wiper Panel Garnish	\$ 11 532.43 X
1	Front Headlamps	\$ 11 561.32 X
1	Front Headlamp Brackets	\$ 11 148.80 X
1	Front Headlamp Lower Seal Rubbers	\$ 11 28.80 X
1	Front Side Lamps	\$ 11 280.37 X
1	Front Signal Lamps	\$ 11 298.98 X
1	Front Panel	\$ 11 1,211.38 X
1	Front Panel "FUSO" Emblem	\$ 11 169.83 X
1	Front Corner Panels	\$ 11 550.78 X
1	Front Side Mirror Stay	\$ 11 252.96 X
1	Front Side Mirror With Stay Assy	\$ 11 781.65 X
1	Front Grille Assy	\$ 11 1,178.08 X
1	Front Grille Logo Sample	\$ 11 98.66 X
1	Front Bumper	\$ 11 1,050.06 X
1	Front Bumper Stay	\$ 11 220.93 X
1	Front Bumper Side O/S	\$ 11 388.98 X
1	Horn	\$ 11 89.00 X
1	Air Con Blower Unit	\$ 11 896.52 X
1	Air Con Cooling Coil	\$ 11 455.00 X
1	Air Con Condenser Discharge Pipe	\$ 11 249.50 X
1	Air Con Condenser Sunction Pipe	\$ 11 285.60 X
1	Front Chasis Cross Member - Ctr	\$ 11 828.65 X
		\$ 10,558.28
	Less 25%	\$ 2,639.57
		\$ 7,918.71
<u>SPECIAL NETT ITEMS</u>		
1	Front Grille Clip	\$ 11 40.00 X
1	Front Number Plate	\$ 11 50.00 X
		\$ 90.00
<u>LABOUR CHARGES</u>		
1	To Check Wiring, Lighting And Resetting Headlamps Focusing	\$ 80.00 20
2	To Remove, Replaced Damaged Lamps & Check Up Wiring	\$ 80.00
3	To Remove And Refit Inner Garnishes	\$ 11 150.00 X
4	To Remove, Replaced Air Condenser, Refill Gas & Conduct Leakage Test	\$ 11 180.00 X
5	To Apply Undercoating.	\$ 11 180.00 X
6	Panel Beating.	\$ 2,000.00 220
7	To Re-spray Painting On The Affected Areas.	\$ 2,000.00 400
		\$ 4,670.00
GRAND TOTAL :		\$ 12,678.71

P-1500.42
252
1125.32
640
1765.32