

ASS. REC. BY:

REF:

LIP / CS/LIP24110339/Kvh3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SNM 3623Z

Policy No.

Claims No. AVS24/3403

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm or

Tyre Size:

F: Dun

R: Dlr

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

/

OTA relate @ 1737.00

26/11

L1 Dmg @ 1500. Carbur (red 9205, 85%)

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trlp:

Survey Fee:

Transportation

S + RS. SI

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 20/11/2024
VEHICLE : FBL7898T
MAKE/MODEL : YAMAHA SNIPER 150 MX
CHASSIS NO : MH3UG0740G0035520
MILLAGE : 3456KM
TYRE SIZE :
DOA : 5/11/2024
TP INSURANCE : LIBERTY

Not Authorized
11 Sep & 15 Sep
Murray After Pain
4 days

List items

01 PC	REAR NUMBER PLATE GARNISH	126	\$ CM	250.00	✓
01 PC	REAR NUMBER PLATE GARNISH BRACKET	53	\$ Bu	80.00	✓
01 PC	REAR NUMBER PLATE LAMP		\$ Bu	60.00	✓
01 PC	REAR SIGNAL LAMP		\$ Lu	45.00	✓
01 PC	REAR BOX		\$ R/L	450.00	220.00
01 PC	REAR BOX BRACKET		\$ R Bu	250.00	X
01 PC	REAR BOX SIDE BRACKET		\$ R	200.00	✓
01 PC	REAR SEAT LOCK		\$ R	140.00	X
01 PC	REAR SWING ARM	420	\$ Bu	850.00	2
01 PC	REAR SWING ARM BUSHING	21.60	\$ R	120.00	2
01 PC	REAR RIM		\$ R	300.00	X
01 PC	REAR CHAIN		\$ Lu	180.00	X
01 PC	REAR SPROCKET		\$ R	150.00	X
01 PC	REAR CHAIN COVER		\$ R	90.00	X
01 PC	REAR FOOT REST		\$ R	40.00	X
01 PC	REAR FOOT REST BRACKET		\$ R	90.00	X
01 PC	MAIN STAND ARM		\$ R	180.00	X
01 PC	FRONT FOOT REST		\$ R/L	40.00	✓
01 PC	GEAR LIVER PADEL		\$ R/L	45.00	✓
01 PC	ENGINE MAGNET COVER		\$ R/L	150.00	X
01 PC	ENGINE MAGNET COVER GASKET		\$ R/L	25.00	X
01 PC	TAIL FAIRING SET		\$ Lu	200.00	X
01 PC	SIDE FAIRING SET		\$ R	250.00	X
01 PC	FRONT FAIRING SET		\$ Lu	200.00	X
01 PC	DASH FAIRING		\$ R/L	150.00	X
01 PC	DASH INNER FAIRING		\$ R	150.00	X
01 PC	FRONT BOX		\$ R/L	350.00	X
01 PC	FRONT BOX BRACKET		\$ R	80.00	X
01 PC	MIRROR LH		\$ R/L	60.00	✓
01 PC	HEAD LAMP COWLING		\$ Lu	180.00	X
01 PC	CLUTCH LEVER		\$ Lu	30.00	X
01 PC	STERRING CONE		\$ R	150.00	X
01 PC	HANDLE BAR		\$ Bu	150.00	2

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

01 PC	HANDLE GRIP
01 PC	HANDLE BALANCER
02 PC	FRONT SIGNAL LAMP @ \$120
02 PC	FRONT POLIT LAMP @ \$100
01 PC	FRONT FENDER
01 PC	FRONT FENDER
01 PC	RADIATOR
02 PC	FRONT FORK @ \$100
01 PC	FRONT FORK BRACKET @ \$100

TOTAL PARTS COST

101

\$	Gr	45.00	✓
NJB		60.00	X
\$	Bn	240.00	X
\$	Bn	200.00	X
\$	Bn	160.00	X
\$	Bn	35.00	X
\$	Bn	250.00	X
\$	Bn	200.00	X
\$	Bn	200.00	X
\$		7,075.00	

Special Nett Item:

01 PC	REAR NUMBER PLATE
01 PC	ENGINE OIL
01 PC	REAR TYRES
01 PC	BODY STICKER
01 PC	FORK OIL
01 PC	FORK SEAL
01 PC	O.B.U

\$	Mit	20.00	15Sn
\$	nn	60.00	X
\$	Sn	150.00	X
\$	nn	200.00	X
\$	nn	60.00	X
\$	nn	60.00	X
246.50Sn 15Sn 10d	\$	380.00	18Sn.
\$		930.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO STRAIGHTEN BODY
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY LABOUR TO ALIGN FRONT BAR

\$	1,000.00	18d1
\$	nn	600.00 X
\$	600.00	10d1
\$	200.00	10d
\$	nn	300.00 X
\$		2,700.00

TOTAL PARTS

SPECIAL NETT ITEM

TOTAL LABOUR

TOTAL COST OF REPAIR

\$	7,075.00
\$	930.00
\$	2,700.00
\$	10,705.00