

ASS. REC. BY:

REF:

LIP/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☒	☒

Bal. or Market Value:

\$5000.

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

FBL 78987

Yr Regn:

031 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha

Shiper mxc.g

150

Colour

Multi Colour

A/C: Insured / Std / NI / NA

Sp. Reading

3456

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MH3UG07406 0035520

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Dun

90/80 R17

R: Dk

120/70 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

2

mm

R/Bal.

4

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

4/11/24

D.O.I.

21/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

2 N/S body

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Transportation

S - RS. SI

: Fines

: Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE	:	20/11/2024
VEHICLE	:	FBL7898T
MAKE/MODEL	:	YAMAHA SNIPER 150 MX
CHASSIS NO	:	MH3UG0740G0035520
MILLAGE	:	3456KM
TYRE SIZE	:	
DOA	:	5/11/2024
TP INSURANCE	:	LIBERTY

Not Authenticated
11 Pump &
Meany After Paint
4 days

List items

01 PC	REAR NUMBER PLATE GARNISH	\$ CM	250.00	✓
01 PC	REAR NUMBER PLATE GARNISH BRACKET	\$ Br	80.00	✓
01 PC	REAR NUMBER PLATE LAMP	\$ Br	60.00	✓
01 PC	REAR SIGNAL LAMP	\$ Cr	45.00	✓
01 PC	REAR BOX	\$	450.00	22cm ✓
01 PC	REAR BOX BRACKET	\$ R Br	250.00	X
01 PC	REAR BOX SIDE BRACKET	\$ R	200.00	✓
01 PC	REAR SEAT LOCK	\$	140.00	?
01 PC	REAR SWING ARM	\$	850.00	?
01 PC	REAR SWING ARM BUSHING	\$	120.00	?
01 PC	REAR RIM	\$ R	300.00	X
01 PC	REAR CHAIN	\$ R	180.00	X
01 PC	REAR SPROCKET	\$ R	150.00	X
01 PC	REAR CHAIN COVER	\$ R	90.00	X
01 PC	REAR FOOT REST	\$ R	40.00	X
01 PC	REAR FOOT REST BRACKET	\$ R	90.00	X
01 PC	MAIN STAND ARM	\$ R	180.00	X
01 PC	FRONT FOOT REST	\$ Del	40.00	✓
01 PC	GEAR LIVER PADEL	\$ Dr	45.00	✓
01 PC	ENGINE MAGNET COVER	\$ R	150.00	X
01 PC	ENGINE MAGNET COVER GASKET	\$ R	25.00	X
01 PC	TAIL FAIRING SET	\$	200.00	?
01 PC	SIDE FAIRING SET	\$ R	250.00	X
01 PC	FRONT FAIRING SET	\$ R	200.00	X
01 PC	DASH FAIRING	\$ R	150.00	X
01 PC	DASH INNER FAIRING	\$ R	150.00	X
01 PC	FRONT BOX	\$ R	350.00	X
01 PC	FRONT BOX BRACKET	\$ R	80.00	X
01 PC	MIRROR LH	\$ Del	60.00	✓
01 PC	HEAD LAMP COWLING	\$ R	180.00	X
01 PC	CLUTCH LEVER	\$ R	30.00	X
01 PC	STERRING CONE	\$ R	150.00	X
01 PC	HANDLE BAR	\$	150.00	?

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

01 PC
01 PC
02 PC
02 PC
01 PC
01 PC
01 PC
02 PC
01 PC
TOTAL PARTS COST

HANDLE GRIP
HANDLE BALANCER
FRONT SIGNAL LAMP @ \$120
FRONT POLIT LAMP @ \$100
FRONT FENDER
FRONT FENDER
RADIATOR
FRONT FORK @ \$100
FRONT FORK BRACKET @ \$100

\$	45.00	✓
NSB	60.00	X
\$	240.00	X
\$	200.00	X
\$	160.00	X
\$	35.00	X
\$	250.00	X
\$	200.00	7
\$	200.00	7
\$	7,075.00	

108

Special Nett Item:

01 PC
01 PC
01 PC
01 PC
01 PC
01 PC
01 PC

REAR NUMBER PLATE
ENGINE OIL
REAR TYRES
BODY STICKER
FORK OIL
FORK SEAL
O.B.U

\$	20.00	150
\$	60.00	X
\$	150.00	X
\$	200.00	X
\$	60.00	7
\$	60.00	7
150JN	380.00	150JN
\$	930.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO STRAIGHTEN BODY
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY LABOUR TO ALIGN FRONT BAR

\$	1,000.00	1000
\$	600.00	X
\$	600.00	1000
\$	200.00	100
\$	300.00	X
\$	2,700.00	

TOTAL PARTS
SPECIAL NETT ITEM
TOTAL LABOUR
TOTAL COST OF REPAIR

\$	7,075.00
\$	930.00
\$	2,700.00
\$	10,705.00