

**Note: This document has not been finalised.**  
**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Crystabelle Tan

Date: 03 Dec 2024

**Preliminary Advice**

|                    |                                                                                                   |                         |                  |
|--------------------|---------------------------------------------------------------------------------------------------|-------------------------|------------------|
| Vehicle No         | : SNM701B                                                                                         | Accident Date           | : 11/11/2024     |
| Make               | : MERCEDES-BENZ C180                                                                              | Policy No.              | : MPC24P00421700 |
| Assignment Date    | : 18/11/2024                                                                                      | Excess                  | : S\$750.00      |
| Date of Inspection | : 21/11/2024                                                                                      | Est. Duration of Repair | : 6              |
| Inspection At      | : DICKSON AUTO CARE CENTRE PTE LTD (HQ)<br>29 UBI ROAD 4, DICKSON AUTO CENTRE<br>SINGAPORE 408619 |                         |                  |

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

|                             |      |                                     |
|-----------------------------|------|-------------------------------------|
| Repairer's Estimate (Gross) | :S\$ | 11,288.70 (inclusive supp \$636.90) |
| Revised Amount              | :S\$ | 7,678.70                            |
| Check Items (Estimated)     | :S\$ | 2,508.00                            |
| Total                       | :S\$ | 10,186.70                           |

Lump Sum Repair :S\$

**Total Loss Consideration**

|                    |      |            |
|--------------------|------|------------|
| New for Old Value  | :S\$ |            |
| Pre-Accident Value | :S\$ | 131,000.00 |
| COE / PARF Rebate  | :S\$ | 104,274.00 |
| Salvage Value      | :S\$ |            |
| Margin for Repair  | :S\$ | 26,726.00  |

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments : Kindly approve on supplementary.