

Dickson Auto Care Centre Pte Ltd (Co.Reg.No:201921404K)

29 Ubi Road 4, Dickson Auto Centre

Singapore 408619

Tel: 6668 1122 Fax: 6668 1123 Email: admin@dacc.com.sg

INSURER:

ECICS Limited (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC24P00421700	Date of Loss:	11/11/2024
Vehicle Reg. No.:	SNM701B	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KOH BEE SOCK	Contact No:	+6591517437
Driver:	TAN LUI		
Make/Model:	MERCEDES-BENZ C180, 1.5 AVANTGARDE LN (A)	Vehicle Reg. Date:	05/11/2014
Vehicle Colour:	METALLIC BLACK		
Engine No:	27491030247273	Chassis No:	WDD2050402R015232
Odometer:	214961 KM		
Paint Type:	PEARL EFFECT		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	DICKSON AUTO CARE CENTRE PTE LTD (HQ)		

COST OF CLAIMS

	Amount
Parts	8,566.80
Miscellaneous Items	115.00
Paintwork Materials	120.00
Labour	1,250.00
Paintwork Labour	600.00
Towing	0.00
Gross Total (S\$)	10,651.80
+ GST 9.00% (S\$)	958.66
Nett Amount (S\$)	11,610.46

This claim is handled by: MAHIRAH MULIANI BINTE BUNTAT

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Nov 2024)

Parts: 143 MERCEDES-BENZ C180 1.5 AVANTGARDE LN (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Dickson Auto Care Centre Pte Ltd/SNM701B/13/11/2024 11:59

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		Air-cond condenser / BT	0.00	0.00	*770.00 F
2	1		Bonnet / (Aluminium)	0.00	0.00	*1,100.00 F
3	10		Bumper clip, front / MC	0.00	0.00	*50.00 F
4	1		Bumper reinforcement, front ?	0.00	0.00	*250.00 F
5	1		Bumper, front / BR	0.00	0.00	*820.00 F
6	1		Headlamp LH / BR	0.00	0.00	*1,720.00 F
7	1		Headlamp RH ?	0.00	0.00	*1,720.00 F
8	1		Panel, front (centre panel) / BT	0.00	0.00	*420.00 F
9	1		*Grille Front / BR	0.00	0.00	*75.00 F
10	1		*Grille Front Cover / BR	0.00	0.00	*125.00 F
11	4		*Grille Front Moulding / BR (or (chrome))	0.00	0.00	*260.00 F
12	1		*Grille Badge [Logo] / MIS	0.00	0.00	*75.00 F
13	1		*Grille Badge Bracket / MIS	0.00	0.00	*48.00 F
14	1		*Bumper Shock Absorber Front ?	0.00	0.00	*150.00 F
15	1		*Bonnet Badge [Logo] / MC	0.00	0.00	*45.00 F
16	1		*Number Base Plate Front ?	0.00	0.00	*90.00 F
17	1		*Grille Front Upper Cover ?	0.00	0.00	*70.00 F

F=Franchise part.

Sub Total (\$\$) 7,788.00
+ Margin on L,N Items 10.00% (\$\$) 778.80

Total Parts (\$\$) 8,566.80

Dickson Auto Care Centre Pte Ltd/SNM701B/13/11/2024 11:59. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Materials			
1	1	Paintwork Materials	X 120.00
Miscellaneous Items			
2	1	Air-cond gas (R134A)	MC / 60.00
3	1	Electrical (check & diagnose)	MC / 17.50
4	1	Number plate front holder	CH / 25.00
5	1	Number plate, front	OK / 12.50
Sub Total (\$\$)			235.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Bonnet	New 200	350.00
2	Bumper, front	New 200	250.00
Labour Items			
3	Bonnet	New	300.00
4	Bumper, front	New	250.00
5	Cooling system	New 600	200.00
6	Bumper reinforcement, front	New	100.00
7	Headlamps Front	New	100.00
8	Panel, front	New	300.00
Gross Labour Cost (\$\$)			1,850.00

Dickson Auto Care Centre Pte Ltd/SNM701B/13/11/2024 11:59. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Steve CLKK
21/10/24, 10.00am
OD - N-1 AL
EX-11 - ?
P/P

By Refor spy
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: