

Dickson Auto Care Centre Pte Ltd (Co.Reg.No:201921404K)

29 Ubi Road 4, Dickson Auto Centre

Singapore 408619

Tel: 6668 1122 Fax: 6668 1123 Email: admin@dacc.com.sg

(SUPPLEMENTARY)INSURER: **ECICS Limited (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC24P00421700	Date of Loss:	11/11/2024
Vehicle Reg. No.:	SNM701B	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	KOH BEE SOCK	Contact No:	+6591517437
Driver:	TAN LUI		
Make/Model:	MERCEDES-BENZ C180, 1.6 AVANTGARDE (R17 LED) (A)	Vehicle Reg. Date:	05/11/2014
Vehicle Colour:	BLACK		
Engine No:	27491030247273	Chassis No:	WDD2050402R015232
Odometer:	215870 KM		
Paint Type:	PEARL EFFECT		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	DICKSON AUTO CARE CENTRE PTE LTD (HQ)		

COST OF CLAIMS**Amount**

Parts	636.90
Miscellaneous Items	0.00
Labour	0.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	636.90
+ GST 9.00% (S\$)	57.32
Nett Amount (S\$)	694.22
+ Previous Estimates (S\$)	11,610.46
Claim Total (S\$)	12,304.68

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS		
Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 03 Dec 2024)
Parts:	143	MERCEDES-BENZ C180 1.6 Avantgarde (R17 LED) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Dickson Auto Care Centre Pte Ltd/SNM701B/03/12/2024 13:15	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BUMPER BRACKET FRONT RH [BELOW HEADLAMP] / BR	0.00	0.00	*55.00 F
2	1		*BUMPER FRONT UNDERCOVER x (Old damaged) NN	0.00	0.00	*120.00 F
3	1		*TOP GRILLE SUPPORT [INNER] / BT	0.00	0.00	*155.00 F
4	1		*BUMPER SIDE RETAINER FRONT LH / BR	0.00	0.00	*12.00 F
5	1		*BUMPER SIDE RETAINER FRONT RH / BR	0.00	0.00	*12.00 F
6	1		*GRILLE RUBBER COVER / BR	0.00	0.00	*95.00 F
7	1		*LOWER GRILLE / BR	0.00	0.00	*90.00 F
8	8		*RIVET / NEC	0.00	0.00	*40.00 F
F=Franchise part.						
Sub Total (\$\$)						579.00
+ Margin on L,N Items 10.00% (\$\$)						57.90
Total Parts (\$\$)						636.90

Dickson Auto Care Centre Pte Ltd/SNM701B/03/12/2024 13:15. Not valid without Reference section.	
Generated using Merimen e-Claims IEAS	

Steve (LKK)
03/12/24

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

There are no labour items selected.

Dickson Auto Care Centre Pte Ltd/SNM701B/03/12/2024 13:15. Not valid without Reference section.
Generated using **Merimen e-Claims IEAS**

< END OF ESTIMATES >