

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 06 Dec 2024

Preliminary Advice

Vehicle No	: SNM701B	Accident Date	: 11/11/2024
Make	: MERCEDES-BENZ C180	Policy No.	: MPC24P00421700
Assignment Date	: 18/11/2024	Excess	: S\$750.00
Date of Inspection	: 21/11/2024	Est. Duration of Repair	: 6
Inspection At	: DICKSON AUTO CARE CENTRE PTE LTD (HQ) 29 UBI ROAD 4, DICKSON AUTO CENTRE SINGAPORE 408619		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,732.70	(Estimate \$10,651.80 + Supp 1 \$636.90 + Supp 2 \$1,444.00)
Revised Amount	:S\$	9,092.70	
Check Items (Estimated)	:S\$	2,508.00	
Total	:S\$	11,600.70	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	131,000.00
COE / PARF Rebate	:S\$	104,274.00
Salvage Value	:S\$	
Margin for Repair	:S\$	26,726.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.