## Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.

AIG Building, 78 Shenton Way

#09-16

Attn:

Singapore 079120

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Wan, Haohui Date: 20 Nov 2024

# **Preliminary Advice**

Vehicle No : SMY3418Z Accident Date : 16/11/2024 Policy No. Make : AUDI Q3 : 7210021293 Assignment Date : 18/11/2024 **Excess** : S\$400.00

Date of Inspection : 18/11/2024 Est. Duration of Repair : 4

Inspection At : 24 BENOI SECTOR

SINGAPORE 629857

REPAIRER: PREMIUM AUTOMOBILES PTE LTD

#### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	27,344.00
Revised Amount	:S\$	14,824.00
Check Items (Estimated)	:S\$	6,461.00
Total	:S\$	21,285.00

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	129,000.00
COE / PARF Rebate	:S\$	52,501.00
Salvage Value	:S\$	

Margin for Repair :S\$ 76,499.00

### Remarks

( x )	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kir	ıdly let us
	have your authorisation.	

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject ( x ) to part prices and labour cost check.