

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0864/2024/KS
DATE : 19-Nov-24
WIP : 38681

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/11/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR TAN CHOON SIONG
ADDRESS : 48 SEA BREEZE AVENUE
SINGAPORE 487567

TELEPHONE : HP +65 98341631
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210021293-03
VEHICLE NO : **SMY 3418 Z**
MODEL CODE : AUDI Q3 1.4 TFSI S TRONIC
MODEL YEAR : 26/2/2021
ENGINE NO : CZD C25465
CHASSIS NO : WAUZZZF33M1067112
MILEAGE : 40,471
DATE IN : 16-Nov-24
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 16-Nov-24
PLACE OF ACCIDENT : YISHUN STREET 44 (DRIVING TOWARDS YISHUN STREET 42)

55 UBI ROAD 1, SINGAPORE 408699


TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMY 3418 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 550.00 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,000.00 750	
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$ 3,000.00 1100	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 292	
TOTAL LABOUR CHARGES		: \$ <u>7,222.00</u>	

2872



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 3418 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>de /</i>	1	\$ 1,388.00	1110.00
2	FRONT BUMPER CLOSING ELEMENT - LH <i>? CM /</i>	1	\$ 74.00	59.04
3	FRONT BUMPER GRILLE - LH <i>SCA /</i>	1	\$ 139.00	110.88
4	FRONT BUMPER CLOSING ELEMENT <i>? X SUC</i>	1	\$ 238.00	
5	FRONT BUMPER SPOILER <i>SCA /</i>	1	\$ 479.00	382.80
6	FRONT BUMPER BRACKET <i>X M</i>	1	\$ 27.00	
7	FRONT BUMPER AIR GUIDE GRILLE - LH <i>CM /</i>	1	\$ 192.00	153.60
8	RADIATOR GRILLE <i>CM /</i>	1	\$ 1,795.00	1436.00
9	RADIATOR GRILLE, STRIKER PLATE <i>? X CM /</i>	1	\$ 303.00	242.40
10	FRONT FOAM FILLER PIECE <i>? X SUC</i>	1	\$ 129.00	
11	FRONT REINFORCEMENT BEAM <i>? X SUC</i>	1	\$ 1,116.00	
12	FRONT BUMPER TOP COVER <i>? X SUC</i>	1	\$ 154.00	
13	FRONT BUMPER GUIDE SECTION - LH <i>CM X SUC</i>	1	\$ 49.00	
14	"CAUTION" STICKER <i>M /</i>	1	\$ 25.00	19.44
15	"A/C" STICKER <i>M /</i>	1	\$ 10.00	7.52
16	FRONT FENDER - LH <i>repair</i>	1	\$ 1,537.00	
17	FRONT FENDER BRACE - LH <i>? X SUC</i>	1	\$ 127.00	
18	FRONT FENDER BRACKET - LH <i>? X SUC</i>	1	\$ 58.00	
19	FRONT WHEEL HOUSING LINER - LH FRONT <i>? X SUC</i>	1	\$ 289.00	
20	FRONT FENDER COVER - LH <i>X SUC</i>	1	\$ 20.00	
SUB TOTAL SPARE PARTS		:	\$ 8,149.00	3521.60

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

65 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMY 3418 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT FENDER CLOSING ELEMENT - LH <i>Xsue</i>	1	\$ 25.00	
22	SIGNAL HORN - LH <i>? Xsue</i>	1	\$ 162.00	
23	HORN BRACKET - LH <i>? Xsue</i>	1	\$ 28.00	
24	HEADLIGHT MOUNTING - LH <i>? ca</i>	1	\$ 147.00	<i>117.60</i>
25	LED HEADLIGHT - LH <i>ca</i>	1	\$ 6,696.00	<i>5356.80</i>
26	LED HEADLIGHT POWER MODULE <i>? Xsue</i>	1	\$ 904.00	
27	LED HEADLIGHT HEAT SINK - LH <i>? Xsue</i>	1	\$ 982.00	
28	HEADLIGHT BREATHER HOSE - LH <i>? Xsue</i>	1	\$ 31.00	
29	LIFT CYLINDER - LH <i>? ca</i>	1	\$ 244.00	<i>195.20</i>
30	LIFT CYLINDER HOSE - LH <i>? Xsue</i>	1	\$ 102.00	
31	WASH WATER RESERVOIR TANK <i>? Xsue</i>	1	\$ 269.00	
32	FRONT PARKING AID SENSOR <i>nw</i>	2	\$ 572.00	<i>457.60</i>
33	FRONT PARKING AID SENSOR SEAL RING <i>n</i>	4	\$ 11.00	<i>8.64</i>
34	FRONT BUMPER WIRING SET <i>? Xsue</i>	1	\$ 804.00	
35	FRONT WHEEL ARCH COVER - LH / RH <i>n</i>	2	\$ 636.00	<i>508</i>
36	FRONT NO PLATE <i>n</i>	S/N	\$ 60.00	<i>✓</i>
37	SUNDRIES <i>? Xnn</i>		\$ 300.00	<i>6703.84</i>
TOTAL SPARE PARTS		:	\$ 20,122.00	
TOTAL LABOUR CHARGES		:	\$ 7,222.00	
GRAND TOTAL		:	\$ 27,344.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

: *Ram - Hp 90010568*
 : *18/11/24*
 : *4 days*
 : *EXCESS: TBA*
 : *Repair*
 : *Reg by paint*

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
 FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT