

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SCJ7108P
TP/China

M/S : CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909

TEL: 63896111

FAX: 62221033

ATTN: Motor Claim Department

WS Ref: TP/CHINA

Claim Type: Third Party

Accident Date: 12/06/2024

TP Veh Reg No: SJW3340J

Claim No: ES2400499

Estimate No: ES2400499/YISHUN

Date: 14 Jun 2024

Policy No: 23-MP005572-R01

Veh Reg No: SCJ7108P

Make/Model: TOYOTA TOYOTA
HARRIER G GRADE

Chassis No: JTEKB3GH20J000975

Engine No: 8ARZ099968

Reg. Date: 30/11/2017

Not Withheld
1/10/24 @ 8:50
Recovery After Paim
10 days

Estimate Repair Cost to Vehicle No : SCJ7108P

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
Cost Plus				
1 REAR BUMPER	280.00	1 PC	280.00	✓
2 REAR BUMPER SPONGE	65.00	1 PC	65.00	✓
3 REAR BUMPER LOWER SKIRT	180.00	1 PC	180.00	✓
4 REAR BUMPER REFLECTOR	35.00	2 PC	70.00	X
5 REAR BUMPER SIDE RETAINER	50.00	2 PC	100.00	✓
6 REAR BUMPER CLIP	2.00	6 PC	12.00	✓
7 REVERSE SENSOR	180.00	2 PC	360.00	✓
8 REAR TAILGATE	620.00	1 PC	620.00	✓
9 TAILGATE INNER LOCK	320.00	1 PC	320.00	✓
10 TAILGATE INNER RUBBER	150.00	1 PC	150.00	✓
11 TAILGATE EMBLEM 'HARRIER'	50.00	1 PC	50.00	✓
12 TAILGATE EMBLEM 'TURBO'	55.00	1 PC	55.00	✓
13 REAR PANEL	380.00	1 PC	380.00	✓
14 REAR PANEL INNER GARNISH	165.00	1 PC	165.00	✓
15 REAR SPARE TYRE COMPARTMENT	490.00	1 PC	490.00	✓
16 REAR SPARE TYRE COMPARTMENT TOP SPONGE	130.00	1 PC	130.00	✓
17 REAR SPARE TYRE HOLDER LOCK	45.00	1 PC	45.00	✓
18 REAR SPARE TYRE COMPARTMENT LH TOOL BOX	280.00	1 PC	280.00	✓
19 REAR SPARE TYRE COMPARTMENT RH TOOL BOX	230.00	1 PC	230.00	✓
20 REAR BALANCING	450.00	1 PC	450.00	✓
21 REAR EXHAUST PIPE	380.00	1 PC	380.00	✓
22 REAR EXHAUST PIPE HOLDER	40.00	1 PC	40.00	X
23 REAR SMART KEY SENSOR	75.00	1 PC	75.00	X
			5,107.00	
	Add 10%		510.70	5,617.70
Special Net				
24 REAR SPARE TYRE PANEL TOP COAT	120.00	1 PC	120.00	90% ✓
25 REAR WINDSCREEN GLASS MOULDING	120.00	1 PC	120.00	✓
26 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
				280.00
Labour				
27 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
16-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896111 **FAX:** 62221033
ATTN: Motor Claim Department

WS Ref: TP/CHINA
Claim Type: Third Party
Accident Date: 12/06/2024
TP Veh Reg No: SJW3340J

Claim No: ES2400499
Estimate No: ES2400499/YISHUN
Date: 14 Jun 2024
Policy No: 23-MP005572-R01
Veh Reg No: SCJ7108P
Make/Model: TOYOTA TOYOTA
HARRIER G GRADE
Chassis No: JTEKB3GH20J000975
Engine No: 8ARZ099968
Reg. Date: 30/11/2017

Estimate Repair Cost to Vehicle No : SCJ7108P

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
28 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE, REAR SPOILER, REAR WIPER ASSY; TO CUTTING, WELDING & RENEW REAR SPARE TYRE COMPARTMENT; KNOCKING & REPAIR REAR FENDERS & REAR SPARE TYRE COMPARTMENT, REINFORCEMENT & REAR CENTRE FLOORBOARD PANEL & REALIGN	1,600.00	1 LA	1,600.00	13001
29 REMOVE & REFIX REAR SEAT, CARPET, GARNISH ETC	120.00	1 LA	120.00	1001
30 REMOVE & REFIX REAR EXHAUST & CHECK SYSTEM	80.00	1 LA	80.00	601
31 REMOVE & REFIX REAR UNDERCARRIAGE	250.00	1 LA	250.00	2001
32 PUTTY & RESPRAY ON REAR CENTRE FLOORBOARD, REAR END PANEL, REAR SPARE TYRE COMPARTMENT, TAILGATE, REAR BUMPER, REAR BOTH FENDERS	1,300.00	1 LA	1,300.00	12001
33 REMOVE & REFIX REAR CAMERA, IN CAR CCTV RECORDER, SMART KEY SENSOR, REVERSE SENSOR & RESET SYSTEM	80.00	1 LA	80.00	601
34 RUSTPROOFING	90.00	1 LA	90.00	✓
				3,620.00

Total S\$ 9,517.70

Add GST @ 9% 856.59

Total Amount payable S\$ 10,374.29

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary items must be resurveyed and
is subject to "without prejudice" from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE