

ASS. REC. BY:

REF: TH /

C

Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____


Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 02 days

Res.: Yes or No

Lum Sum: 1. B. 1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: PLC 7858MYr Regn: 05, 16Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy Axiomc.c. 1496Colour: M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 137002

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: _____

NRE161 0017036Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: _____

205/50R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mmR/Bal. 7 mmL/Bal. 4 mmL/Bal. 7 mmD.O.A. 25/6/24D.O.I. 15/7/2024

Survey held at _____

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orRear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/8 @ 1183.18 Cash

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Add Fee: ☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech Invs (\$)

☐

Weekend (\$)

Transportation

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLC7858M
TP/India

M/S : INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04/#05 IOB BUILDING
SINGAPORE 049711

TEL: 63476100 FAX: 62247743
ATTN: Motor Claim Department

WS Ref: TP/INDIA
Claim Type: Third Party
Accident Date: 25/06/2024
TP Veh Reg No: SJU4892L

Estimate No: ES2400573/YISHUN
Date: 15 Jul 2024
Policy No: MP308672
Veh Reg No: SLC7858M
Make/Model: TOYOTA COROLLA
AXIO 1.5X A
Chassis No: NRE1610017036
Engine No: 2NR8608166
Reg. Date: 25/05/2016

Not Notion
Repair B & pain
2 days
81183-18

Estimate Repair Cost to Vehicle No :SLC7858M

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 REAR BUMPER	779.40	1 PC	779.40	—
2 REAR BUMPER LH SIDE RETAINER	150.50	1 PC	150.50	—
3 REAR BUMPER CLIP	3.50	6 PC	21.00	—
			950.90	
		Less 25%	237.73	713.18
Special Net				
4 REAR BUMPER LH BODY PROTECTOR	50.00	1 PC	50.00	—
			50.00	50.00
Labour				
5 REMOVE & REFIX REAR BUMPER, REVERSE SENSOR ASSY; KNOCKING & REPAIR REAR LH FENDER LOWER & REALIGN THE SAME	300.00	1 LA	300.00	200
6 PUTTY & RESPRAY ON REAR BUMPER, REAR LH FENDER	400.00	1 LA	400.00	220
			700.00	700.00
			Total	S\$ 1,463.18
			Add GST @ 9%	131.69
			Total Amount Payable	S\$ 1,594.87

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before the spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- To be resurveyed and approved on "Without Prejudice" basis
- To be resurveyed and approved by the Insurance Company

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE