

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875

Tel: 93290237 Email: claims_rar@bifrotauto.com

SJE :

Date of Survey :

Date of ReSurvey:

Contacts :

Vehicle Nos : SNF 7551H

Made : Honda

Model : Shuttle 1.5 Hybrid

Chassis No : GP71218434

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount:

Working Day:

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper / BR	1	\$ 1,050.50	\$ / 1,050.50
2	Front Bumper Side Retainer RH X nn	1	\$ 18.00	\$ / 18.00
3	Front Bumper Side Retainer LH / BR	1	\$ 18.00	\$ 18.00
4	Front Bumper Fog Lamp Garnish LH X nn	1	\$ 90.10	\$ 90.10
5	Front Bumper Lower Grille X nn	1	\$ 140.20	\$ 140.20
6	Front Bumper Reinforcement X nn	1	\$ 297.20	\$ 297.20
7	Front Bumper Tow Cover X nn	1	\$ 25.10	\$ 25.10
8	Front Grille Base X nn	1	\$ 298.60	\$ 298.60
9	Front Grille Outer Chrome Garnish X nn	1	\$ 398.50	\$ 398.50
10	Front Grille Lower Chrome X nn	1	\$ 220.70	\$ 220.70
11	Front Grille Emblem X nn	1	\$ 27.40	\$ 27.40
12	Front Headlamp Assembly RH X nn	1	\$ 2,521.50	\$ 2,521.50
13	Front Headlamp Lower Bracket RH X nn	1	\$ 47.50	\$ 47.50
14	Front Headlamp Chrome Moulding RH X nn	1	\$ 105.40	\$ 105.40
15	Front Headlamp Assembly LH / CUT	1	\$ 2,521.50	\$ 2,250 / 2,521.50
16	Front Headlamp Lower Bracket LH X nn	1	\$ 47.50	\$ 47.50
17	Front Headlamp Chrome Moulding LH X nn	1	\$ 105.40	\$ 105.40
18	Front Support Panel X nn	1	\$ 749.40	\$ 749.40
19	Front Support Panel Top Garnish X nn	1	\$ 212.60	\$ 212.60
20	Front Bonnet X nn	1	\$ 966.50	\$ 966.50
21	Front Fender LH / DD	1	\$ 509.40	\$ / 509.40
22	Front Fender Inner Shield LH X nn	1	\$ 120.50	\$ 120.50
23	Front Fender Emblem LH / MC	1	\$ 38.00	\$ / 38.00
24	Front Door Side Mirror Assembly LH X nn	1	\$ 573.60	\$ 573.60
25	Front Door Side Mirror Cover LH X nn	1	\$ 55.00	\$ 55.00
26	Front Door LH X nn	1	\$ 785.80	\$ 785.80
27	Front Door Upper Hinge LH X nn	1	\$ 48.20	\$ 48.20

	Front Door Lower Hinge LH	X nn	1	\$	48.20	\$	48.20
	Front Door Checker LH	X nn	1	\$	56.60	\$	56.60
	Front Door Weatherstrip LH	X nn	1	\$	82.60	\$	82.60
	Front Door Lock Assembly LH	X nn	1	\$	265.80	\$	265.80
	Front Door Frame Sticker LH	X nn	1	\$	38.00	\$	38.00
3	Front Door Window Glass Regulator Gear LH	X	1	\$ nn	378.00	\$	378.00
34	Front Door Inner Trim Board LH	X nn	1	\$	581.00	\$	581.00
35	Rocker Panel LH	X nn	1	\$	584.20	\$	584.20
36	Rocker Panel Garnish LH	X nn	1	\$	398.60	\$	398.60
37	Front Shock Absorber LH	X nn	1	\$	386.90	\$	386.90
38	Front Lower Arm LH	X nn	1	\$	309.10	\$	309.10
39	Front Knuckle Arm LH	X nn	1	\$	330.80	\$	330.80
40	Front Wheel Bearing LH	X nn	1	\$	170.50	\$	170.50

3865.90
-20%
3092.72

Parts Sub Total : \$ 15,622.40
20% Discount \$ 3,124.48
PARTS TOTAL : \$ 12,497.92

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate X nn	1	\$ 50.00	\$ 50.00
2	Front Fender Inner Shield LH Clips - Set X nn	1	\$ 50.00	\$ 50.00
3	Front Bumper Clips - Set / APC	1	\$ 50.00	\$ 30 50.00
4	Front Bonnet Sealant X nn	1	\$ 150.00	\$ 150.00
5	Front Fender LH Sealant X nn	1	\$ 150.00	\$ 150.00
6	Front Door LH Sealant X nn	1	\$ 150.00	\$ 150.00
7	Rocker Panel LH Sealant X nn	1	\$ 150.00	\$ 150.00
8	Front Fender Glass Sealant LH X nn	1	\$ 120.00	\$ 120.00
9	Radiator Coolant X nn	1	\$ 60.00	\$ 60.00
10	Front Tyre LH X nn	1	\$ 350.00	\$ 350.00
11	Front Wheel Rim LH / RM	1	\$ 1,200.00	\$ 400 1,200.00
430 SPECIAL NETT TOTAL :				\$ 2,480.00

Nos.	LABOUR	S\$ TOTAL
1	To Panel Beat, Remove & Refix Parts	\$ 400 2,000.00
2	To Spray Paint Affected Areas	\$ 400 1,600.00
3	Wiring & Bulb Check	\$ 30 100.00
4	To Transfer Front Door LH Mechanism	\$ X 150.00
5	To Remove & Refix Front Fender LH Glass	\$ X 150.00
6	To Remove & Refix Aircon Condenser and Top Up Gas	\$ X 150.00
7	To Remove & Refix Radiator and Pressure Test	\$ X 150.00
8	To Remove & Refix Front Undercarriage	\$ X 450.00

To Remove & Refix Tyres and Conduct Wheel Balancing	\$ 70 20	150.00
To Conduct Four Wheel Alignment	\$ 80	150.00
To apply anti rust on affected parts	\$ 20	200.00
To Conduct Water Leak Test	\$ X	100.00
To Send Diagnostic & Reset Control Unit. Programming & Calibration	\$ X	480.00
	950	LABOUR TOTAL :
		\$ 5,830.00

PARTS TOTAL : \$ 12,497.92

SPECIAL NETT TOTAL : \$ 2,480.00

LABOUR TOTAL : \$ 5,830.00

GRAND TOTAL : \$ 20,807.92

Steve (LKK)

19/11/24, 1.00 PL

m IL

L/S

L AC L
4 dy

4472.72

L/S - 3578.17
= 3600

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: