



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMX 2308U

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER FASCIA	BUCKLED/CRACKED	\$471.00	\$471.00
1	REAR BUMPER LOWER SPOILER	SERVICEABLE	\$341.00	\$0.00
1	REAR BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	\$295.00	\$0.00
2	BUMPER REINFORCEMENT TOP BKT @\$18.00	TO REPAIR SEE LABOUR	\$36.00	\$0.00
3	BUMPER REINFORCEMENT LOW BKT @\$18.00	TO REPAIR SEE LABOUR	\$54.00	\$0.00
2	REAR BUMPER REFLECTOR @\$151.00	SERVICEABLE	\$302.00	\$0.00
2	REAR BUMPER LICENSE PLATE LAMP @\$30.00	SERVICEABLE	\$60.00	\$0.00
2	REAR CENTRE PARKING SENSOR @\$170.00	SERVICEABLE	\$340.00	\$0.00
1	BOOT LID	TO REPAIR SEE LABOUR	\$2,025.00	\$0.00
1	BOOT LID "AVANTE" EMBLEM	NECESSARY	\$32.00	\$32.00
1	BOOT LID "S" EMBLEM	NECESSARY	\$42.00	\$42.00
1	BOOT LID CENTRE REFLECTOR	SERVICEABLE	\$1,028.00	\$0.00
	LESS 20.00% DISCOUNT		(\$1,005.20)	(\$109.00)
			\$4,020.80	\$436.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REWIRING REAR PARKING SENSOR WIRE		\$30.00	\$30.00
	TO PUTTY AND SPRAY REPLACED PARTS		\$600.00	\$400.00
	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT, BUMPER REINFORCEMENT TOP BKT, BUMPER REINFORCEMENT LOW BKT AND BOOT LID		\$500.00	\$400.00
			\$1,130.00	\$830.00

GRAND TOTAL			\$5,150.80	\$1,266.00
	RECOMMENDED COST OF REPAIRS			\$1,266.00
Report Ref No: CS/AGI24110352/Kvp3e2				

KSC

KENNETH KONG SENG CHEONG



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.