

# WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

*Not Authorized*

*for*  
*Merus*

*19/11/24*

18 November 2024

REG NO. : SLR 1131 L  
MAKE/MODEL : HONDA GRACE

*2/5 @ 6500 /  
after repair*

*5 days*

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear windscreen moulding	\$ 11 115.00 X
1	Rear boot lid	\$ 800.00 1,288.90 X
1	Rear boot chrome clip (1 set)	\$ 11 75.00 X
1	Rear boot outer chrome moulding	\$ CR 320.30
1	Rear boot top spoiler	\$ CR 1,106.90
2	Rear boot hinges	\$ 600 90-20 0/5 TR 180.40 IPC
1	Rear boot inner trim	\$ 11 260.80 X
2	Rear boot lamps	\$ CR 783.80
1	Rear boot inner lock	\$ TR 195.00
1	Rear boot logo	\$ TR 28.20
1	Rear boot weatherstrip	\$ TR 129.60
1	Rear boot "GRACE" emblem	\$ TR 55.60
1	Rear boot "HYBRID" emblem	\$ TR 68.30
2	Rear number plate lamps	\$ CR 170.00
2	Rear taillamps	\$ CR 450x2=900 1,358.80
2	Rear taillamp panels	\$ 299 600 n/sr 0/5 TR 890.40 IPC
1	Rear end panel	\$ 600 813.70
1	Rear end panel inner garnish	\$ 300.00 215.00
1	Rear bumper	\$ 632.50 1,000.70
1	Rear bumper inner sponge	\$ TR 99.10 X
2	Rear bumper reflectors	\$ 65.30 0/5 CR 130.60 IPC
2	Rear bumper side retainers	\$ 11 97.20 X
1	Rear floor panel	\$ 2 855.30 X
1	Rear floor board	\$ 394.20 455.00
1	Rear fender -RH	\$ 1,414.60 X
2	Rear fender inner trim boards	\$ 394.10 n/sr 0/5 Del/Ten 801.80 IPC
		\$ 12,910.00
	Less 20%	\$ 2,582.00
		\$ 10,328.00

SPECIAL NETT ITEMS

1	Rear windscreen sealant	\$	11	80.00	X
1	Rear bumper clip (1 set)	\$	121	80.00	30
1	Rear number plate with holder	\$	SVC	50.00	X
1	Rear reverse sensor (1 set)	\$	modification	350.00	200
1	Rear reverse camera	\$	81	600.00	X
		\$		1,160.00	

S/N      LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$		80.00	20
2	To remove and refit inner garnishes.	\$		150.00	60
3	To remove and refit rear reverse sensor and camera.	\$		150.00	30
4	To transfer boot lid mechanism and wiring assembly.	\$		80.00	50
5	To remove and refit rear windscreen glass.	\$	~^	180.00	X
6	To apply undercoating.	\$		200.00	60
7	Panel beating.	\$		2,000.00	800
8	To re-spray painting on the affected areas.	\$		1,800.00	1200
		\$		4,640.00	

**GRAND TOTAL :**

**\$ 16,128.00**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-7235  
202  
5788.  
230  
220