

FONG MOTORS

TO	: ERGO	DATE	: 18/11/2024
VEHICLE NO	: SNK4409E (2016)		Veron
VEHICLE MODEL	: MINI COOPER		
CHASSIS NO	: WMWXS52000C89095		

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER <i>Deland</i>	1	\$ 914.00	\$ 914.00
2	REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 45.00	\$ 90.00
3	REAR BUMPER INNER BRACKET <i>LH cracked</i>	2	\$ 181.00	\$ 362.00
4	REAR BUMPER REFLECTOR <i>new</i>	2	\$ 152.00	\$ 152.00
5	REAR BUMPER REFLECTOR CHROME RING <i>not ne</i>	1	\$ 92.00	\$ 92.00
6	REAR BUMPER TOW COVER <i>new</i>	2	\$ 38.00	\$ 76.00
7	REAR BUMPER SENSOR <i>1 piece dmd</i>	4	\$ 251.00	\$ 1,004.00
8	REAR BUMPER SENSOR HOLDER <i>new</i>	4	\$ 25.00	\$ 100.00
9	REAR BUMPER LOWER GARNISH <i>Deland</i>	1	\$ 285.00	\$ 285.00
10	REAR END PANEL <i>3HP</i>	1	\$ 512.00	\$ 512.00
11	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 159.00	\$ 159.00
12	TAILLAMP <i>LH cracked</i>	2	\$ 498.00	\$ 996.00
13	TAILLAMP CHROME RING <i>not ne</i>	2	\$ 54.00	\$ 108.00
14	TAILGATE <i>Deland</i>	1	\$ 1,245.00	\$ 1,245.00
15	TAILGATE LOCK <i>dmd</i>	1	\$ 192.00	\$ 192.00
16	TAILGATE WEATHERSTRIPE <i>new</i>	1	\$ 209.00	\$ 209.00
17	TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 405.00	\$ 405.00
18	TAILGATE GLASS MOULDING <i>new</i>	1	\$ 185.00	\$ 185.00
19	COOPER WORDING <i>new</i>	1	\$ 89.00	\$ 89.00
20	REAR EXHAUST PIPE <i>new</i>	1	\$ 1,090.00	\$ 1,090.00
21	REAR EXHAUST PIPE MOUNTING <i>2</i>	1	\$ 54.00	\$ 54.00
22	REAR EXHAUST PIPE GASKET <i>new</i>	1	\$ 45.00	\$ 45.00
23	REAR EXHAUST PIPE HEAT SHIELD <i>new</i>	1	\$ 124.10	\$ 124.10
24	REAR FENDER ARC GARNISH <i>new</i>	2	\$ 196.00	\$ 392.00
25	REAR FENDER INNER SHIELD <i>new</i>	2	\$ 147.50	\$ 295.00
26	REAR FENDER INNER TRIM BOARD <i>new</i>	2	\$ 305.20	\$ 610.40

Rear Bumper Reinforcement 558
new

TOTAL PRICE: \$ 9,785.50
LESS 10% \$ 978.55
SUB TOTAL PRICE: \$ 8,806.95

3830

3447

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR BUMPER CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
2	REAR END PANEL TOP GARNISH CLIPS (SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	REAR END PANEL SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00
4	TAILGATE INNER TRIM BOARD CLIPS (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
5	TAILGATE GLASS SEALANT <i>new</i>	1	\$ 60.00	\$ 60.00

TOTAL : \$ 200.00

230

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,200.00	400 450	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	400	
3	WIRING CHECK	\$ 100.00	30	
4	TO REMOVE REVERSE SENSOR	\$ 100.00	50	
5	TO REMOVE UPHOLSTERY	\$ 150.00	X	
6	TO SPRAY TUFF COAT	\$ 150.00	X	
7	TO REMOVE REAR EXHAUST PIPE	\$ 150.00	X	
8	TO TRANSFER TAILGATE FITTINGS	\$ 150.00	60	
9	TO REPLACE TAILGATE GLASS	\$ 180.00	120	
		TOTAL \$ 3,180.00		

1060

ESTIMATE REPORT

TOTAL PARTS COST: \$ 9,006.95

TOTAL LABOUR COST: \$ 3,180.00

TOTAL REPAIR COST: \$ 12,186.95

Total: 4737

L/s: 3.8K

0.5 Days.

3.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: