

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

**REPAIR ESTIMATE SLE5154H**

Not Authorized  
21 Sep 8:10, 004  
Penny After Paint  
6 days

| No. | Qty   | Nett Items                                           |        |          |             |
|-----|-------|------------------------------------------------------|--------|----------|-------------|
| 1   | 1     | Front RH fender                                      | 483    | \$       | 948.10 ✓    |
| 2   | 1     | Front RH fender lower black wheel arch garnish       |        | \$       | 654.00 ✓    |
| 3   | 1     | Front RH fender lower black wheel arch garnish clips |        | \$       | 40.00 ✓     |
| 4   | 1     | Front RH fender under shield                         |        | \$       | 175.00 ✓    |
| 5   | 1 set | Front fender under shield clips                      |        | \$       | 40.00 ✓     |
| 6   | 1     | Front RH lower arm                                   |        | \$       | 269.00 ✓    |
| 7   | 1     | Front RH door                                        |        | \$       | 1,384.10 ✓  |
| 8   | 1 set | Front RH door black sticker                          |        | \$       | 36.00 ✓     |
| 9   | 1     | Front RH door lower black protector                  |        | \$       | 370.20 ✓    |
| 10  | 2     | Front RH door top hinge (Top & bottom)               |        | \$       | 139.80 X    |
| 11  | 1     | Front RH door checker                                |        | \$       | 58.60 X     |
| 12  | 1     | Front RH door weatherstrip                           | 82.65m | \$       | 165.30 502m |
| 13  | 1     | Front RH door inner trim board                       |        | \$       | 1,576.70 ✓  |
| 14  | 1 set | Front RH door inner trim board clips                 |        | \$       | 60.00 ✓     |
| 15  | 1     | Front RH door inner lock                             |        | \$       | 397.10 X    |
| 16  | 1     | Front RH door glass channel                          |        | \$       | 208.00 ✓    |
| 17  | 1     | Front RH door glass regulator & motor                | 915.60 | \$       | 1,273.10 ✓  |
| 18  | 1     | Rear RH door lower black protector                   |        | \$       | 238.20 ✓    |
|     |       |                                                      |        | \$       | 8,033.20    |
|     |       |                                                      |        | Less 10% | \$ 803.32   |
|     |       |                                                      |        | Total :  | \$ 7,229.88 |

| Special Nett Items |   |                              |                                                                  |        |                   |
|--------------------|---|------------------------------|------------------------------------------------------------------|--------|-------------------|
| 19                 | 1 | Front RH tyre                | LKK Auto Consultants hence notify the Repairer of the following: | \$     | 240.00 802m 1821m |
| 20                 | 1 | Front RH sports rim          | • To resurvey before/after spray painting                        | \$     | 1,819.00 16d1-50  |
| 21                 | 1 | Front RH shock absorber      | • To display damaged part(s) during resurvey                     | \$     | 606.10 ✓          |
| 22                 | 1 | Front RH knuckle arm         | • Parts prices are subject to confirmation                       | \$     | 657.60 ✓          |
| 23                 | 1 | Front RH wheel hub & bearing | • Third party survey is on a "Without Prejudice" basis           | \$     | 376.10 ✓          |
|                    |   |                              |                                                                  | \$     | 3,698.80          |
|                    |   |                              |                                                                  | Total: | \$ 3,698.80       |

| <u>Labour</u> |                                                                                             | Acknowledged by Repairer |       |             |      |
|---------------|---------------------------------------------------------------------------------------------|--------------------------|-------|-------------|------|
|               |                                                                                             | Signature:               | Date: |             |      |
| 1             | Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages. |                          |       | \$ 800.00   | 500d |
| 2             | To putty and spray Spray Paintings charges.                                                 |                          |       | \$ 800.00   | 700d |
| 3             | To remove, refit front RH door fittings.                                                    |                          |       | \$ 80.00    | 60d  |
| 4             | To check wirings.                                                                           |                          |       | \$ 40.00    | 20d  |
| 5             | To remove, refit front RH under carriage damage parts.                                      |                          |       | \$ 220.00   | 200d |
| 6             | To conduct computerise wheel alignment test.                                                |                          |       | \$ 100.00   | 60d  |
| 7             | To supply and apply anti rust treatment.                                                    |                          |       | \$ 80.00    | 60d  |
| Total :       |                                                                                             |                          |       | \$ 2,120.00 |      |

**Total Parts and Labour : \$ 13,048.68**



# 源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

18.11.2024

## SUPPLEMENTARY REPAIR ESTIMATE FOR Nissan Qashqai - SLE 5154 M

| <u>Special Nett Items</u> |                                  |     |             |             |
|---------------------------|----------------------------------|-----|-------------|-------------|
| 1 pc.                     | Front RH drive shaft             | As  | \$ 1,837.30 | SN ✓        |
| 1 pc.                     | Front RH shock absorber mounting | As  | \$ 107.60   | SN ✓        |
| 1 pc.                     | Front RH shock absorber bearing  | As  | \$ 96.10    | SN ✓        |
| 1                         | Towing Charges                   |     | \$ 60.00    | SN ✓        |
|                           |                                  | 107 | TOTAL       | \$ 2,101.00 |