



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H








LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 5 of 19)

PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 8 of 19)

PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H







PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H





PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H




PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H





PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H



PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 19 of 19)

PHOTOGRAPHS FOR VEHICLE NO. : SMK 5577H

