

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TP Budget Direct.
Xiao Chan.

AW KIM LENG
633A PUNGGOL DRIVE #08-675
SINGAPORE 821633

TAX INVOICE

Repair Code : CLM16476

Date in : 17/11/2024

Vehicle Num. : SMK5577H

Model : HONDA FREED HYBRID 1.5G AUTO

Chassis/Eng# : GB71091722/LEB5630696

Contact : 81896841

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT AIR DUCT <i>Not in</i>	1	38.00	+ 38.00
FRONT AIRCON CONDENSER <i>Deletd</i>	1	985.00	✓ 985.00
FRONT AIRCON CONDENSER ALUMINIUM PIPE <i>3 in</i>	1	180.00	+ 180.00
FRONT AIRCON CONDENSER DISCHARGE PIPE <i>3 in</i>	1	298.00	+ 298.00
FRONT AIRCON CONDENSER FAN BLADE <i>3 in</i>	1	68.00	+ 68.00
FRONT AIRCON CONDENSER FAN COWLING <i>3 in</i>	1	81.60	+ 81.60
FRONT AIRCON CONDENSER FAN MOTOR <i>3 in</i>	1	315.20	+ 315.20
FRONT BONNET <i>Not in</i>	1	720.00	+ 720.00
FRONT BONNET HINGES L/R	2	45.60	+ 91.20
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R	2	10.80	+ 21.60
FRONT BONNET INNER SIDE RUBBER SEAL L/R <i>Not in</i>	2	36.00	+ 72.00
FRONT BONNET INNER TOP RUBBER L/R	2	19.50	+ 39.00
FRONT BONNET MECHANISM LOCK <i>Not in</i>	1	153.20	+ 153.20
FRONT BUMPER <i>Deletd</i>	1	1050.00	✓ 1,050.00
FRONT BUMPER LOWER GRILLE <i>Deletd</i>	1	180.00	✓ 180.00
FRONT BUMPER LOWER RUBBER LID <i>Not in</i>	1	90.50	✓ 90.50 X
FRONT BUMPER REINFORCEMENT <i>Deletd</i>	1	295.00	✓ 295.00
FRONT BUMPER SIDE RETAINER L/R <i>Not in</i>	2	19.50	+ 39.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

AW KIM LENG
633A PUNGGOL DRIVE #08-675
SINGAPORE 821633

Contact : 81896841

TAX INVOICE

Repair Code : CLM16476

Date in : 17/11/2024

Vehicle Num. : SMK5577H

Model : HONDA FREED HYBRID 1.5G AUTO

Chassis/Eng# : GB71091722/LEB5630696

FRONT BUMPER TOW HOOK COVER	<i>Deformed</i>	1	15.40	✓	15.40
FRONT FENDER 'HYBRID' EMBLEM L/R	<i>new</i>	2	65.90	✓	131.80
FRONT FENDER L/R	<i>Repair</i>	2	440.00	+	880.00
FRONT GRILLE 'LOGO' EMBLEM	<i>new</i>	1	18.00	✓	18.00
FRONT GRILLE CENTER BRACKET	<i>crushed</i>	1	65.00	✓	65.00
FRONT GRILLE WITH CHROME	<i>crushed</i>	1	869.96	✓	869.96
FRONT HEADLAMP L/R	<i>crushed</i>	2	1980.00	✓	3,960.00
FRONT HEADLAMP LOWER BRACKET L/R	<i>crushed</i>	2	36.50	✓	73.00
FRONT HORN	<i>new</i>	1	48.60	+	48.60
FRONT SUPPORT PANEL	<i>Buckled</i>	1	702.80	✓	702.80
RADIATOR (AUTO)	<i>Deformed</i>	1	1502.00	✓	1,502.00
RADIATOR FAN BLADE	<i>new</i>	1	87.50	+	87.50
RADIATOR FAN COWLING		1	105.00	+	105.00
RADIATOR FAN MOTOR		1	336.00	+	336.00
RADIATOR GUIDE		1	128.00	+	128.00
RADIATOR LOWER SIDE GUIDE	<i>new</i>	1	88.00	+	88.00
RADIATOR SPARE TANK	<i>Deformed</i>	1	65.80	✓	65.80
REAR BUMPER	<i>Deformed</i>	1	1017.50	✓	1,017.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

AW KIM LENG
 633A PUNGGOL DRIVE #08-675
 SINGAPORE 821633

Contact : 81896841

TAX INVOICE

Repair Code : CLM16476

Date in : 17/11/2024

Vehicle Num. : SMK5577H

Model : HONDA FREED HYBRID 1.5G AUTO

Chassis/Eng# : GB71091722/LEB5630696

REAR BUMPER INNER GARNISH L/R	<i>Not in</i>	2	50.90	+	101.80
REAR BUMPER LOWER COVER	<i>Not in</i>	1	279.00	+	279.00
REAR BUMPER REFLECTOR L/R	<i>Not in</i>	2	42.80	+	85.60
REAR BUMPER SIDE BRACKET L/R	<i>Not in</i>	2	30.50	✓	61.00
REAR BUMPER SIDE RETAINER L/R	<i>Not in</i>	2	33.10	+	66.20
REAR BUMPER TOW HOOK COVER	<i>Not in</i>	1	18.50	✓	18.50
REAR END PANEL (INNER)	<i>Dented</i>	1	453.80	✓	453.80
REAR END PANEL (OUTER)	<i>Dented</i>	1	623.70	✓	623.70
REAR END PANEL CENTER BRACKET L/R	<i>Not in Bent</i>	2	18.50	✓	37.00
REAR END PANEL INNER TOP GARNISH	<i>Not in</i>	1	115.00	✓	115.00
REAR FENDER INNER TRIM BOARD L/R	<i>Not in</i>	2	356.00	✓	712.00
REAR FLOOR PANEL	<i>Repair</i>	1	1056.00	✓	1,056.00
REAR FLOOR PANEL LOWER JACK PANEL	<i>Not in</i>	1	50.00	+	50.00
REAR FLOOR PANEL TRIM CARPET	<i>Not in</i>	1	950.00	✓	950.00
REAR TAILGATE	<i>Dented</i>	1	1326.10	✓	1,326.10
REAR TAILGATE 'FREED' EMBLEM	<i>Not in</i>	1	63.00	✓	63.00
REAR TAILGATE 'HYBRID' EMBLEM	<i>Not in</i>	1	85.00	✓	85.00
REAR TAILGATE 'LOGO' EMBLEM	<i>Not in</i>	1	32.50	✓	32.50

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

AW KIM LENG
 633A PUNGGOL DRIVE #08-675
 SINGAPORE 821633

Contact : 81896841

TAX INVOICE

Repair Code : CLM16476

Date in : 17/11/2024

Vehicle Num. : SMK5577H

Model : HONDA FREED HYBRID 1.5G AUTO

Chassis/Eng# : GB71091722/LEB5630696

REAR TAILGATE DAMPER L/R	<i>new</i>	2	135.00	<i>f</i>	270.00
REAR TAILGATE HINGES L/R		2	50.00	<i>f</i>	100.00
REAR TAILGATE INNER ANTENNA SENSOR	<i>new</i>	1	58.10	<i>f</i>	58.10
REAR TAILGATE INNER PULL HANDLE	<i>new</i>	1	25.00	<i>f</i>	25.00
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R	<i>new</i>	2	12.50	<i>+</i>	25.00
REAR TAILGATE INNER TRIM BOARD	<i>could</i>	1	378.00	<i>✓</i>	378.00
REAR TAILGATE LOCK STRIKER	<i>new</i>	1	27.50	<i>+</i>	27.50
REAR TAILGATE MECHANISM LOCK	<i>Damaged</i>	1	189.90	<i>✓</i>	189.90
REAR TAILGATE NUMBER PLATE LAMP L/R	<i>new</i>	2	38.50	<i>+</i>	77.00
REAR TAILGATE OUTER CHROME GARNISH	<i>could</i>	1	320.40	<i>✓</i>	320.40
REAR TAILGATE OUTER LOCK SWITCH	<i>new</i>	1	175.50	<i>✓</i>	175.50
REAR TAILGATE REFLECTOR L/R	<i>could</i>	2	360.00	<i>✓</i>	720.00
REAR TAILGATE REVERSE CAMERA	<i>new</i>	1	1194.60	<i>+</i>	1,194.60
REAR TAILGATE WEATHER STRIP	<i>new</i>	1	168.00	<i>✓</i>	168.00
REAR TAILGATE WINDSCREEN MOULDING	<i>new</i>	1	120.00	<i>✓</i>	120.00
REAR TAILLAMP CLIPS L/R	<i>new</i>	4	3.50	<i>+</i>	14.00
REAR TAILLAMP L/R	<i>could</i>	2	629.10	<i>✓</i>	1,258.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

AW KIM LENG
633A PUNGGOL DRIVE #08-675
SINGAPORE 821633

TAX INVOICE

Repair Code : CLM16476

Date in : 17/11/2024

Vehicle Num. : SMK5577H

Model : HONDA FREED HYBRID 1.5G AUTO

Chassis/Eng# : GB71091722/LEB5630696

Contact : 81896841

		Subtotal before discount	26,049.06
Percentage discount	20%	18814.56	5,209.81
		Sub-total 1	20,839.25
FRONT BONNET INSULATOR CLIPS - SET	1	50.00	50.00
FRONT BUMPER CLIPS - SET	1	80.00	80.00
FRONT BUMPER NUMBER PLATE	1	25.00	25.00
FRONT BUMPER NUMBER PLATE HOLDER	1	50.00	50.00
FRONT GRILLE CLIPS - SET	1	40.00	40.00
RADIATOR COOLANT	1	80.00	80.00
REAR BUMPER CLIPS - SET	1	80.00	80.00
REAR BUMPER REVERSE SENSOR - SET	1	250.00	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	1	30.00	30.00
REAR END PANEL SEALANT	1	100.00	100.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET	2	50.00	100.00
REAR FLOOR PANEL INSULATOR MAT	1	280.00	280.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET	1	50.00	50.00
REAR TAILGATE NUMBER PLATE	1	25.00	25.00
REAR TAILGATE NUMBER PLATE HOLDER	1	50.00	50.00
REAR TAILGATE OUTER CHROME GARNISH CLIPS - SET	1	40.00	40.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

AW KIM LENG
633A PUNGGOL DRIVE #08-675
SINGAPORE 821633

Contact : 81896841

TAX INVOICE

Repair Code : CLM16476

Date in : 17/11/2024

Vehicle Num. : SMK5577H

Model : HONDA FREED HYBRID 1.5G AUTO

Chassis/Eng# : GB71091722/LEB5630696

REAR TAILGATE WINDSCREEN SEALANT <i>rev</i>	1	80.00	<i>60</i> 80.00
Subtotal before discount			1,410.00
Percentage discount 0%			0.00
Sub-total 2			1,410.00
Parts-total			22,249.25

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To re-spray painting on the front bonnet, front support panel, front fender (L/R) and front bumper.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	5,940.00
Parts & Labour Total	28,189.25

*** This is a computer-generated document which requires no signature. ***

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 6

Adrian L
2/18/11/24
13 Days
total: 19416.64
2/15/11/24