

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24110359/TVP3M4**Date:** 27/11/2024**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MN000301		
Claimant Vehicle No :	SHA6278B	Insured Vehicle No :	YP1922C		
Date of Loss:	16/11/2024	Nature of Claim:	TP	Claim No:	M2406728

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA6278B	Engine No:	G4LEJU191068
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU141197
Reg. Date:	01/03/2019 (Man. Year: 2018)	Odometer:	475754 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65R15	Rear Tyre Size:	195/65R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	624.08	492.32	131.76	21.11
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	760.00	690.00	70.00	9.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,396.08	1,194.32	201.76	14.45
Approved Total (Overridden) (S\$)		950.00		
(S\$)	1,396.08	950.00	446.08	31.95
+ GST 9.00/9.00% (S\$)	125.65	85.50	40.15	31.95
Nett Amount (S\$)	1,521.73	1,035.50	486.23	31.95

INSPECTION

Date of Assignment:	19/11/2024 Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang) COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)
Date Inspected:	19/11/2024 Inspected At:	59 LOYANG DRIVE SINGAPORE 508969
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2024)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA6278B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER LH	Bent	588.80 FL	*588.80 FL
2	1		*EMBLEM- BLUE DRIVE LH	Necessary	26.60 FL	*26.60 FL
3	1		*FRT FENDER SHIELD LH	Not Necessary	164.70 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					Sub Total (\$\$)	780.10 615.40
					- List Item Discount on L Items 20.00/20.00% (\$\$)	156.02 123.08
					Total Parts (\$\$)	624.08 492.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING CHARGE	New	300.00	280.00
3	TUFF KOTE	New	60.00	30.00
Gross Labour Cost (\$\$)			760.00	690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >