

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Daphne

LONPAC INSURANCE BHD

300 Beach Road #17-04/07

The Concourse

Singapore 199555

Tel : 6250 - 7388

Fax : 6296 - 2706

Quotation

DATE : 19.11.2024

VEH NO : SNQ4559Z

MODEL : Mercedes A200

D O A : 18.11.2024

YR REF : XD4712Y

Attn : Motor Claim Dept

(Pls arrange vehicle surveyor & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SNQ4559Z (MERCEDES A200)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<u>NO</u>	<u>LIST ITEMS</u>		
1	Rear Bumper <i>torn</i>	1	1,770.00 ✓
2	Rear Bumper Side Holder - RH <i>Not nec</i>	1	145.00 X
3	Rear Bumper Reflector - RH <i>new</i>	1	96.00 +
4	Rear Bumper Sensor <i>new</i>	2	510.00 X
5	Rear Bumper Sensor Holder <i>new</i>	4	100.00 ✓
6	Tail Lamp - RH <i>cracked</i>	1	786.00 ✓
7	Tail Lamp Panel - RH <i>Dented</i>	1	245.00 ✓
8	Rear Fender - RH <i>Distorted</i>	1	2,623.00 ✓
9	Rear Fender Inner Shield - RH <i>torn</i>	1	214.00 ✓
10	Rear Fender Air Vent <i>Not nec</i>	1	65.00 X
11	Rear Door - RH <i>Dented</i>	1	2,588.00 ✓
12	Rear Door Lock - RH <i>new</i>	1	298.00 +
13	Rear Door Weatherstripe - RH <i>new</i>	1	318.00 ✓
14	Rear Wheel Rim - RH <i>new</i>	1	1,310.00 X
15	Rear Upper Arm	1	571.00 +
16	Rear Lower Arm	1	835.00 +
17	Rear Knuckle Arm	1	1,315.00 X
18	Rear Control Arm	1	219.00 X
19	Rear Wheel Hub C/w Bearing	1	599.00 X
20	Rear Shock Absorber	1	636.00 +

Less 10%

\$	15,243.00
	(1,524.30)
\$	13,718.70

S/NETT ITEMS

1	Rear Bumper Clips	1 set	50.00 ✓
2	Rear Fender Inner Shield Clips	1 set	30.00 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SNQ4559Z (MERCEDES A200)

3	Rear Fender Sealant <i>Mer</i>	340	1 set	60.00	<i>✓</i>
4	Rear Tyre <i>lt</i>		1	350.00	<i>2w</i>
				490.00	

Total Parts \$ 14,208.70

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00	1000
2	To putty & spray up paint works	\$	1,000.00	700
3	To check wiring system	\$	50.00	30
4	To spray tuff coat	\$	150.00	80
5	To remove reverse sensor	\$	100.00	50
6	To transfer rear door fittings	\$	150.00	80
7	To remove upholstery	\$	150.00	80
8	To dismantle rear undercarriage	\$	350.00	x
9	To perform wheel alignment	\$	150.00	80
10	To perform diagnostic test	\$	200.00	150
Total Labour		\$	3,500.00	

Grand Total **\$ 17,708.70**

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 10369.60
h/s: 8.3K.
07 Days