



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24060280/Tvh3e2
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	27/06/2024
SINGAPORE 048583	Code:	LIP

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SNR 846R	Veh. Inspected	SMK 3959C
Policy No.	-	Coverage	0
Claim No.	IVS24/1207	Excess	\$0.00
Assign From	ANDY SEAH	Assign Date	26/06/2024

### 2. Vehicle Details

Make & Model	TOYOTA SIENTA	C.C	1496
Engine No.	2NRX442211	Year of Reg.	09/04/2019
Chassis No.	MHFZ28H3000063179	Colour	BEIGE
Odometer	66258 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/50 R16	MICHELIN	6
L/H Front Tyre	195/50 R16	MICHELIN	6
R/H Rear Tyre	195/50 R16	MICHELIN	6
L/H Rear Tyre	195/50 R16	MICHELIN	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	23/06/2024	Inspection Date	27/06/2024
Survey held at	AUTOBACS CAR CARE (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days