



AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.

8 Kaki Bukit Ave, 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
 Tel : 6702 1555 Fax : 6702 1444
 Co. Reg No. : 201500047H GST No. : 201500047H
 Email : admin@autobacs.com.sg

TO	Liberty (SNR846R)	DATE	: 24-Jun-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXXX592C	P -	
		S -	
		L -	
VEHICLE DETAILS		TOTAL	:
VEHICLE NO.	: SMK3959C	L/S -20%	:
MODEL / MAKE	: Toyota Sienta	SUB TOTAL	:
CHASSIS NO.	: MHFZ28H3000063179		
ACCIDENT DETAIL			
DATE	: 23-Jun-24		
TIME	: 11:25HRS	CONTACT PERSON	: MR. SIM 9844 0974

QUOTATION SUMMARY PAGE 01
 CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	front headlamp Rh	1	\$ 4,887.00	\$ 4,887.00
2	front fender Rh	1	\$ 813.00	\$ 813.00
3	front fender bracket Rh	1	\$ 159.00	\$ 159.00
4	front fender inner shield Rh	1	\$ 245.00	\$ 245.00
5	front fender inner shield stay clips Rh	2	\$ 18.00	\$ 36.00
6	front bumper	1	\$ 478.00	\$ 478.00
7	front bumper top rubber seal (stick on)	1	\$ 79.00	\$ 79.00
8	front bumper fog lamp garnish Rh	1	\$ 178.00	\$ 178.00
9	front bumper side retainer Rh	1	\$ 98.00	\$ 98.00
10	front 16" sport rim Rh	1	\$ 2,785.00	\$ 2,785.00
11	Bonnet R			
TOTAL PRICE				\$ 9,758.00
LESS -25%				\$ (2,439.50)
SUB TOTAL PRICE				\$ 7,318.50

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	front fender inner shield clips set Rh	1	\$ 60.00	\$ 60.00
2	front bumper clips set	1	\$ 80.00	\$ 80.00
TOTAL				\$ 140.00

QUOTATION SUMMARY

PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 800.00	450	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 800.00	450	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 75.00	30	
TO PERFORM LIGHTING & WIRING CHECK	\$ 120.00	30	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 120.00	80	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 380.00	X	

TOTAL \$ 2,295.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 7,458.50
 TOTAL LABOUR COST : \$ 2,295.00
 TOTAL REPAIR COST : \$ 9,753.50

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS

REPAIR UNDER : PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY : Tanjir 97495749/62563561
 27/6/24 2230 pm

SURVEYED BY / FROM :

CONTACT NUMBER

EMAIL ADDRESS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanjir @ 11/11/2024

3 days

Resurvey after repair