

## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 19/11/2024
User ID : kokkhoon

Section A - Accident Details				
Registration Number	SG6116Z			
Case Reference Number	BUS/11/24/5032			
Registration Date	2/4/2019			
Company Type	SMRT Buses Ltd			
Make	MAN			
Model	MAN A95 EU6			
Name of Driver	Zhang Chao			
Type of Accident	Side Swipe			
Accident Date and Time	15/11/2024 3:16 PM			
Accident Reported Date and Time	18/11/2024 4:50 PM			
Is Surveyor Required?	Yes			
Survey by				
Vehicle is Towed Back?	No			
Towed Back Date and Time				
Replacement Vehicle issued?	No			
Job Card Number				
Special Instruction to ARC,if any	SG6116Z - Front right windscreen and front right body panel cracked SKU8184J (TP) - INSURED WITH CHINA TAIPING			
Prepared Date and Time	19/11/2024 10:29 AM			
Chassis Number				
Mileage				
Work Shop				
Repair Completion Date and Time				

	Section B - Summary of Repair Estimates					
Summary of Repair Estimates						
	Quotation from ARC	Adjusted by Surveyor, if applicable				
Total Labour Cost	\$2,120.00	\$0.00				
Total Spray Cost	\$786.00	\$0.00				
Total Spare Part Cost	\$6,639.40	\$0.00				
Total Other Cost	\$500.00	\$0.00				
TOTAL COST	\$10,045.40	\$0.00				
Lump Sum Total	\$10,050.00	\$0.00				
Number of Repair Days	4.0					
Prepared / Adjusted By	ARC Manager Team					
ARC / Surveyor Sign Off Date	19/11/2024 10:42 AM					
Signature	9	×				
Remarks						

Section C - Quotation and Accident Invoice Details							
Quotation Number		Invoice Number					
Quotation Date		Invoice Date					
Invoice Amount		Prepared Date					

Steve (LKK) 19/11/24, 5.00 pm Without Prejudice 3 days L/S Resurvey After Spray



## **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 19/11/2024
User ID : kokkhoon

			Section	on D - Deta	ils of Repair E	stimates			
Part 1 - Labou	ır Works								
Job Scope			Quotation from AR				Adjusted by Surveyo	r, if applicable	
		OVE ITEMS AND	REPAIR OTHERS	\$2,120.00				1500	
DAMAGED AFFECTED AREAS.			20,400,00				1590		
Total Labour				\$2,120.00					
Part 2 - Spray	Painting & Pan	el Beating Rela	ited Works						
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00				616		
			\$786.00						
Part 3 - Other	Costs - Acciden	nt and Accident	t Repair Related Expens	se				1	
Job Scope				Quotation fr	rom ARC			Adjusted by Surveyo	r, if applicable
TOWING CHAR	RGE			\$500.00				/ NEC	
Total Other Costs			\$500.00						
Part 4 - Spare	Parts / Material	Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6013532	GLASS	124-4-2-001- 023	FRONT WINDSCREEN FW3	1.00	\$4,107.50	10.00	\$3,696.75	Replace	/ BR
4006315	CONSUMABLE	Aktivator - 100	ACTIVATOR	1.00	\$80.00	0.00	\$80.00	Replace	/ Nec
4006314			SEALANT SIKAFLEX	10.00	\$37.00	0.00	\$370.00	Replace	/ Nec
4006313	CONSUMABLE	SIKA® Primer- 206 G+P	PRIMER (SIKA 206 G+P)	1.00	\$80.00	0.00	\$80.00	Replace	/ Nec
6013840			HEADLAMP:RH (RIGHT SIDE),MAN A95 EURO 6	1.00	\$1,675.00	10.00	\$1,507.50	Replace	?
6013472	Body	124-2-2-009- 001	FRP FRONT DOME	1.00	\$3,430.00	100.00	\$0.00	Repair	x Repair
6013471	Body	124-2-2-009- 002	O/S FRP FRONT HEADLAMP COVER	1.00	\$975.00	10.00	\$877.50	Replace	/ BR
6013474	Body	124-2-2-009- 004	FRP FRONT BUMPER	1.00	\$1,875.00	10.00	\$1,687.50	Replace	/ BR
Total					\$12,259.50		\$8,299.25		
Added Spare	Parts / Material	Usage After Su	rveyor Signed off		·				
					List Price \$	T	Final Price (\$)	Lead	1-
Part Number	Portion	Stock Number		Quantity		Discount (%)	1	1	Surveyor Check

Total