



MY CAR CONSULTANT PTE LTD

Reg no.: 201605878Z

Address: 60 JALAN LAM HUAT, CARROS CENTRE 05-68 S737896

HP: 98888885

Estimation

Date: 19/11/2024

Vehicle: SNA2413H

Make / Model: TOYOTA PRIUS

No.	Description	Unit	Unit Price	Amount	
	Parts Replacement:				
1	REAR BUMPER / BR	1	\$ 798.00	\$ 798.00	503 /
2	REAR BUMPER SIDE RETAINER RH / BR	1	\$ 112.00	\$ 112.00	/
3	REAR BUMPER LOWER LID x nn	1	\$ 598.00	\$ 598.00	
4	REAR FENDER RH X R	1	\$ 621.00	\$ 621.00	
5	TAILAMP RH X nn	1	\$ 512.00	\$ 512.00	
	TOTAL PART			\$ 2,641.00	615.00
	LIST DOWN	25%		\$ 660.25	-25%
	AFTER LIST DOWN			\$ 1,980.75	461.25
	SPEICAL NETT				
1	REAR BUMPER CLIPS	1	\$ 50.00	\$ 50.00	30 /
2	REAR WHEEL HUB CAP RH	1	\$ 100.00	\$ 100.00	x nn
	TOTAL AMOUNT			\$ 150.00	30
	LABOUR				
1	CHECK WIRING	1	\$ 100.00	\$ 100.00	30 /
2	REMOVE AND REPAIR REAR BUMPER SENSOR	1	\$ 150.00	\$ 150.00	30 /
3	PANEL BEAT EFFECTED AREAS	1	\$ 400.00	\$ 400.00	/
4	REPAIR EFFECTED AREAS	1	\$ 600.00	\$ 600.00	400
	TOTAL AMOUNT			\$ 1,620.00	
			Parts Replacement Amount	\$ 1,852.50	860
			Total Amount for Labour	\$ 1,250.00	
			Total Amount	\$ 3,102.50	

Steve (LKK)
19/11/24, 4.30pm
Without Prejudice
4 days
L/S
Resurvey After Spray

1351.25

L/S - 1081.00
= 1100